

		GOVERNMENT OF NEWFOUNDLAND AND LABRADOR Department of Transportation and Infrastructure		BRIDGE INSPECTION REPORT B07302025-8	
Date: 10/24/2024		Inspected By: M.Snooks		Category: Eng. - Engineering	
BRIDGE INFORMATION					
Site:		TCH-165 - FIRST AVENUE OVERPASS (WESTBOUND) - R			
SUBSTRUCTURE					
Condition:	F2 - Fair	Bearings:	I - Inapplicable		
		Bearing Seat:	I - Inapplicable		
Comments:	Vegetation growing out of the headwalls				
SUPERSTRUCTURE					
Condition:	F2 - Fair	Expansion Joints:	F1 - Fair		
Comments:	Spalling and cracking on soffit with exposed rebar. Expansion joints paved over.				
DECK					
Condition:	F1 - Fair	Curbs:	I - Inapplicable		
Hand Rail:	I - Inapplicable	Roadway Condition:	F1 - Fair		
Approach Rail:	F2 - Fair				
Comments:	Moderate amount of winter sand built up at bottom of barrier wall. Some cracking at asphalt joins. Pothole adjacent to expansion joint				
HYDROLOGY					
Water Velocity:	0 m/s	Ice Problem:	NA - Not Applicable		
Water Depth:	0 m	Scour Problem:	NA - Not Applicable		
Waterway:	03 - Not Applicable	Debris Problem:	NA - Not Applicable		
Comments:					
REPLACEMENT/REHABILITATION					
Next Rehab. Date:		Replacement Year:			
Antic. Rehab. Cost:	\$0	Replacement Cost:	\$0		
Recommendations:					
OBSERVATIONS					
Overall Condition:	F2 - Fair	Requires Further Inspection:	No		
Additional Observations:					

Department of Transportation and Infrastructure, Government of Newfoundland and Labrador 2026.