

		GOVERNMENT OF NEWFOUNDLAND AND LABRADOR Department of Transportation and Infrastructure		BRIDGE INSPECTION REPORT B09112025-3	
Date: 9/11/2025		Inspected By: Megan/Heidi		Category: Office - Bridge Office	
BRIDGE INFORMATION					
Site:		TCH-075 - FISCHER'S BROOK BRIDGE - R1			
SUBSTRUCTURE					
Condition:		G - Good		Bearings: G - Good	
				Bearing Seat: G - Good	
Comments:		Abutments excellent condition. Some hairline cracking in wingwalls.			
SUPERSTRUCTURE					
Condition:		G - Good		Expansion Joints: G - Good	
Comments:		Girders and diaphragms in excellent condition.			
DECK					
Condition:		G - Good		Curbs: G - Good	
Hand Rail:		G - Good		Roadway Condition: F2 - Fair	
Approach Rail:		F2 - Fair			
Comments:		Deck excellent condition. Pattern hairline cracking in jersey barrier. Rotten timber posts in approach rail.			
HYDROLOGY					
Water Velocity:		n/a m/s		Ice Problem: NA - Not Applicable	
Water Depth:		n/a m		Scour Problem: NA - Not Applicable	
Waterway:		01 - Adequate		Debris Problem: NA - Not Applicable	
Comments:		N/A			
REPLACEMENT/REHABILITATION					
Next Rehab. Date:		Replacement Year:			
Antic. Rehab. Cost:		\$0		Replacement Cost: \$0	
Recommendations:		N/A			
OBSERVATIONS					
Overall Condition:		G - Good		Requires Further Inspection: No	
Additional Observations:		Refer to detailed OSIM inspection.			

Department of Transportation and Infrastructure, Government of Newfoundland and Labrador 2026.