

		GOVERNMENT OF NEWFOUNDLAND AND LABRADOR Department of Transportation and Infrastructure		BRIDGE INSPECTION REPORT B09092025-6	
Date: 9/2/2025		Inspected By: Megan/Heidi		Category: Office - Bridge Office	
BRIDGE INFORMATION					
Site:		4-032 - GADONS BROOK BRIDGE - R460			
SUBSTRUCTURE					
Condition:	G - Good	Bearings:	I - Inapplicable		
		Bearing Seat:	I - Inapplicable		
Comments:	Medium cracks noted in abutment #1. Light erosion on bottom of abutment #2. Otherwise good to excellent condition of abutments and wingwalls.				
SUPERSTRUCTURE					
Condition:	G - Good	Expansion Joints:	I - Inapplicable		
Comments:					
DECK					
Condition:	G - Good	Curbs:	G - Good		
Hand Rail:	G - Good	Roadway Condition:	G - Good		
Approach Rail:	G - Good				
Comments:	Full length medium cracks in deck interior soffit (2). Pattern medium cracks. Hairline cracking in deck soffit. 0.5 m crack with efflorescence in exterior soffit				
HYDROLOGY					
Water Velocity:	n/a m/s	Ice Problem:	NA - Not Applicable		
Water Depth:	n/a m	Scour Problem:	NA - Not Applicable		
Waterway:	01 - Adequate	Debris Problem:	NA - Not Applicable		
Comments:	N/A				
REPLACEMENT/REHABILITATION					
Next Rehab. Date:		Replacement Year:			
Antic. Rehab. Cost:	\$0	Replacement Cost:	\$0		
Recommendations:	Replace missing hazard signs (4).				
OBSERVATIONS					
Overall Condition:	G - Good	Requires Further Inspection:	No		
Additional Observations:	Stream affecting abutment #1 more than abutment #2. Refer to BMS for detailed OSIM inspection.				

Department of Transportation and Infrastructure, Government of Newfoundland and Labrador 2026.