

		GOVERNMENT OF NEWFOUNDLAND AND LABRADOR Department of Transportation and Infrastructure		BRIDGE INSPECTION REPORT B11142025-2	
Date: 9/11/2025		Inspected By: M. Pederson/S. Walsh		Category: Office - Bridge Office	
BRIDGE INFORMATION					
Site:		4-168 - HUGHES BROOK BRIDGE - R440			
SUBSTRUCTURE					
Condition:	G - Good	Bearings:	G - Good		
		Bearing Seat:	G - Good		
Comments:	Medium cracks are present in both Abutment 1 and Abutment 2. Spalling is observed on Girder 3.				
SUPERSTRUCTURE					
Condition:	G - Good	Expansion Joints:	G - Good		
Comments:	The hazard sign is missing on the left-hand side of Abutment 1. Medium cracks have been observed in the curb.				
DECK					
Condition:	G - Good	Curbs:	G - Good		
Hand Rail:	G - Good	Roadway Condition:	G - Good		
Approach Rail:	G - Good				
Comments:	A small crack with efflorescence is visible on the soffit near Abutment 1.				
HYDROLOGY					
Water Velocity:	0 m/s	Ice Problem:	N - No Problem		
Water Depth:	0 m	Scour Problem:	N - No Problem		
Waterway:	01 - Adequate	Debris Problem:	N - No Problem		
Comments:					
REPLACEMENT/REHABILITATION					
Next Rehab. Date:		Replacement Year:			
Antic. Rehab. Cost:	\$0	Replacement Cost:	\$0		
Recommendations:					
OBSERVATIONS					
Overall Condition:	G - Good	Requires Further Inspection:	No		
Additional Observations:	Refer to detailed OSIM inspection in BMS for more information.				

Department of Transportation and Infrastructure, Government of Newfoundland and Labrador 2026.