

		GOVERNMENT OF NEWFOUNDLAND AND LABRADOR Department of Transportation and Infrastructure		BRIDGE INSPECTION REPORT B09112025-1	
Date: 9/11/2025		Inspected By: Megan/Heidi		Category: Office - Bridge Office	
BRIDGE INFORMATION					
Site:		TCH-072 - LITTLE BARACHOIS BROOK BRIDGE - R			
SUBSTRUCTURE					
Condition:	G - Good	Bearings:	U - Uninspectable		
		Bearing Seat:	U - Uninspectable		
Comments:	Some hairline cracking in abutments, otherwise excellent condition. Hairline cracking in wingwalls. Small area of rust staining in abutment #1 wingwall right hand side.				
SUPERSTRUCTURE					
Condition:	G - Good	Expansion Joints:	F1 - Fair		
Comments:	Girders and diaphragms in excellent condition. Some areas of poor to severe honeycombing. Leakage noted at curbs of seals.				
DECK					
Condition:	G - Good	Curbs:	G - Good		
Hand Rail:	G - Good	Roadway Condition:	G - Good		
Approach Rail:	F2 - Fair				
Comments:	Deck and soffit in excellent condition. Hairline cracking in jersey barrier. Rotten timber posts in approach rail.				
HYDROLOGY					
Water Velocity:	n/a m/s	Ice Problem:	NA - Not Applicable		
Water Depth:	n/a m	Scour Problem:	NA - Not Applicable		
Waterway:	01 - Adequate	Debris Problem:	NA - Not Applicable		
Comments:	N/A				
REPLACEMENT/REHABILITATION					
Next Rehab. Date:		Replacement Year:			
Antic. Rehab. Cost:	\$0	Replacement Cost:	\$0		
Recommendations:	N/A				
OBSERVATIONS					
Overall Condition:	G - Good	Requires Further Inspection:	No		
Additional Observations:	See BMS for detailed OSIM inspection.				

Department of Transportation and Infrastructure, Government of Newfoundland and Labrador 2026.