

		GOVERNMENT OF NEWFOUNDLAND AND LABRADOR Department of Transportation and Infrastructure		BRIDGE INSPECTION REPORT B07302025-11	
Date: 10/30/2024		Inspected By: C.Spencer		Category: Eng. - Engineering	
BRIDGE INFORMATION					
Site:		TCH-138 - MASSEY DRIVE OVERPASS (EASTBOUND) - R			
SUBSTRUCTURE					
Condition:		F2 - Fair		Bearings: I - Inapplicable	
				Bearing Seat: I - Inapplicable	
Comments:					
SUPERSTRUCTURE					
Condition:		F1 - Fair		Expansion Joints: I - Inapplicable	
Comments: Some minor spalling and efflorescence on deck soffit.					
DECK					
Condition:		F1 - Fair		Curbs: F2 - Fair	
Hand Rail:		F1 - Fair		Roadway Condition: F1 - Fair	
Approach Rail:		F2 - Fair			
Comments: Damage to end of handrail. Asphalt delaminating from deck at end of approach.					
HYDROLOGY					
Water Velocity:		0 m/s		Ice Problem: NA - Not Applicable	
Water Depth:		0 m		Scour Problem: NA - Not Applicable	
Waterway:		03 - Not Applicable		Debris Problem: NA - Not Applicable	
Comments:					
REPLACEMENT/REHABILITATION					
Next Rehab. Date:				Replacement Year:	
Antic. Rehab. Cost:		\$0		Replacement Cost: \$0	
Recommendations:					
OBSERVATIONS					
Overall Condition:		F2 - Fair		Requires Further Inspection: No	
Additional Observations:					

Department of Transportation and Infrastructure, Government of Newfoundland and Labrador 2026.