

		GOVERNMENT OF NEWFOUNDLAND AND LABRADOR Department of Transportation and Infrastructure		BRIDGE INSPECTION REPORT B10162024-9	
Date: 10/4/2024		Inspected By: Scott Wight		Category: Eng. - Engineering	
BRIDGE INFORMATION					
Site:		TCH-133 - MOLLICHIGNICK BRIDGE - R1			
SUBSTRUCTURE					
Condition:	F2 - Fair	Bearings:	I - Inapplicable		
		Bearing Seat:	I - Inapplicable		
Comments:	Minor spalling and staining on both abutments.				
SUPERSTRUCTURE					
Condition:	F2 - Fair	Expansion Joints:	I - Inapplicable		
Comments:	Minor cracking and spalling on the exterior face of the reinforced slab (upstream and downstream).				
DECK					
Condition:	F2 - Fair	Curbs:	F2 - Fair		
Hand Rail:	P3 - Poor	Roadway Condition:	F2 - Fair		
Approach Rail:	F1 - Fair				
Comments:	Hand rail damaged on both sides. Spalling on deck soffit. Deck drains full of sand/debris.				
HYDROLOGY					
Water Velocity:	0 m/s	Ice Problem:	N - No Problem		
Water Depth:	0 m	Scour Problem:	N - No Problem		
Waterway:	01 - Adequate	Debris Problem:	N - No Problem		
Comments:					
REPLACEMENT/REHABILITATION					
Next Rehab. Date:		Replacement Year:			
Antic. Rehab. Cost:	\$TBD	Replacement Cost:	\$TBD		
Recommendations:					
OBSERVATIONS					
Overall Condition:	F2 - Fair	Requires Further Inspection:	No		
Additional Observations:					

Department of Transportation and Infrastructure, Government of Newfoundland and Labrador 2026.