

		GOVERNMENT OF NEWFOUNDLAND AND LABRADOR Department of Transportation and Infrastructure		BRIDGE INSPECTION REPORT B11142025-4	
Date: 9/11/2025		Inspected By: M. Pederson/S. Walsh		Category: Office - Bridge Office	
BRIDGE INFORMATION					
Site:		4-101 - McIVER'S BROOK BRIDGE - R440			
SUBSTRUCTURE					
Condition:	F1 - Fair	Bearings:	U - Uninspectable		
		Bearing Seat:	U - Uninspectable		
Comments:	No major issues, past rehab patches are holding up well.				
SUPERSTRUCTURE					
Condition:	F1 - Fair	Expansion Joints:	U - Uninspectable		
Comments:	Cracking with efflorescence and rust staining visible between Girder 5-6. Low cover spalling present on girders. Expansion joints paved over. Recent rehab on girders looks good.				
DECK					
Condition:	U - Uninspectable	Curbs:	I - Inapplicable		
Hand Rail:	P - Poor	Roadway Condition:	P3 - Poor		
Approach Rail:	F1 - Fair				
Comments:	Light erosion around approach rail posts. Handrail is not attached in most places and easily moved, not safe and replacement required. Soffit interior not accessible due to girders, soffit cantilever and fascia in P3.				
HYDROLOGY					
Water Velocity:	0 m/s	Ice Problem:	P - Possible Problem		
Water Depth:	0 m	Scour Problem:	N - No Problem		
Waterway:	01 - Adequate	Debris Problem:	N - No Problem		
Comments:					
REPLACEMENT/REHABILITATION					
Next Rehab. Date:		Replacement Year:			
Antic. Rehab. Cost:	\$0	Replacement Cost:	\$0		
Recommendations:					
OBSERVATIONS					
Overall Condition:	P3 - Poor	Requires Further Inspection:	No		
Additional Observations:	Replace handrails. Please refer to detailed OSIM inspection for more details.				

Department of Transportation and Infrastructure, Government of Newfoundland and Labrador 2026.