

		GOVERNMENT OF NEWFOUNDLAND AND LABRADOR Department of Transportation and Infrastructure		BRIDGE INSPECTION REPORT B07222025-7	
Date: 9/26/2024		Inspected By: Colby Spencer		Category: Eng. - Engineering	
BRIDGE INFORMATION					
Site:		4-018 - PARSON'S POND BRIDGE - R			
SUBSTRUCTURE					
Condition:	F1 - Fair	Bearings:	U - Uninspectable		
		Bearing Seat:	U - Uninspectable		
Comments:	Scour at base of abutments and piers. Deterioration at top of wing walls. Some efflorescence at cracking. Cracking on piers				
SUPERSTRUCTURE					
Condition:	F2 - Fair	Expansion Joints:	F2 - Fair		
Comments:	Expansion joints filled with sand and rusting efflorescence on exterior girder. Some minor cracking and efflorescence apparent on soffit.				
DECK					
Condition:	F2 - Fair	Curbs:	F1 - Fair		
Hand Rail:	F2 - Fair	Roadway Condition:	F1 - Fair		
Approach Rail:	F2 - Fair				
Comments:	Pot hole in deck filled with cold patch. Light cracking on curb and sidewalk.				
HYDROLOGY					
Water Velocity:	0 m/s	Ice Problem:	P - Possible Problem		
Water Depth:	0 m	Scour Problem:	P - Possible Problem		
Waterway:	01 - Adequate	Debris Problem:	N - No Problem		
Comments:					
REPLACEMENT/REHABILITATION					
Next Rehab. Date:		Replacement Year:			
Antic. Rehab. Cost:	\$0	Replacement Cost:	\$0		
Recommendations:					
OBSERVATIONS					
Overall Condition:	F1 - Fair	Requires Further Inspection:	No		
Additional Observations:	Rusting in power conduit				

Department of Transportation and Infrastructure, Government of Newfoundland and Labrador 2026.