

		GOVERNMENT OF NEWFOUNDLAND AND LABRADOR Department of Transportation and Infrastructure		BRIDGE INSPECTION REPORT B10242025-6	
Date: 8/20/2025		Inspected By: C.Spencer		Category: Eng. - Engineering	
BRIDGE INFORMATION					
Site:		TCH-167 - PASADENA EAST INTERCHANGE (WESTBOUND) - R			
SUBSTRUCTURE					
Condition:	F2 - Fair	Bearings:	U - Uninspectable		
		Bearing Seat:	G - Good		
Comments:					
SUPERSTRUCTURE					
Condition:	F2 - Fair	Expansion Joints:	F1 - Fair		
Comments: Some very minor discoloration on outside deck fascia. Some damage to expansion joints on deck.					
DECK					
Condition:	F1 - Fair	Curbs:	G - Good		
Hand Rail:	G - Good	Roadway Condition:	F1 - Fair		
Approach Rail:	F1 - Fair				
Comments: Light settlement noted on both approach slabs; transverse cracking also noted at the approach slab/road transition. Moderate damage noted on one section of the approach rail.					
HYDROLOGY					
Water Velocity:	0 m/s	Ice Problem:	NA - Not Applicable		
Water Depth:	0 m	Scour Problem:	NA - Not Applicable		
Waterway:	03 - Not Applicable	Debris Problem:	NA - Not Applicable		
Comments:					
REPLACEMENT/REHABILITATION					
Next Rehab. Date:		Replacement Year:			
Antic. Rehab. Cost:	\$0	Replacement Cost:		\$0	
Recommendations:					
OBSERVATIONS					
Overall Condition:	F2 - Fair	Requires Further Inspection:	No		
Additional Observations:					

Department of Transportation and Infrastructure, Government of Newfoundland and Labrador 2026.