

		GOVERNMENT OF NEWFOUNDLAND AND LABRADOR Department of Transportation and Infrastructure		BRIDGE INSPECTION REPORT B07302025-4	
Date: 10/24/2024		Inspected By: M.Snooks		Category: Eng. - Engineering	
BRIDGE INFORMATION					
Site:		TCH-159 - PASADENA WEST ACCESS (WESTBOUND) - R			
SUBSTRUCTURE					
Condition:		F2 - Fair	Bearings:		I - Inapplicable
			Bearing Seat:		I - Inapplicable
Comments:					
SUPERSTRUCTURE					
Condition:		F1 - Fair	Expansion Joints:		I - Inapplicable
Comments:		Stress cracks observed on deck soffit with water seepage and efflorescence noted.			
DECK					
Condition:		F1 - Fair	Curbs:		I - Inapplicable
Hand Rail:		I - Inapplicable	Roadway Condition:		F1 - Fair
Approach Rail:		F1 - Fair			
Comments:		Cracking and potholes in the asphalt around the approach slabs. Significant accumulation of winter sand barrier wall.			
HYDROLOGY					
Water Velocity:		0 m/s	Ice Problem:		NA - Not Applicable
Water Depth:		0 m	Scour Problem:		NA - Not Applicable
Waterway:		03 - Not Applicable	Debris Problem:		NA - Not Applicable
Comments:					
REPLACEMENT/REHABILITATION					
Next Rehab. Date:			Replacement Year:		
Antic. Rehab. Cost:		\$0	Replacement Cost:		\$0
Recommendations:					
OBSERVATIONS					
Overall Condition:		F1 - Fair	Requires Further Inspection:		No
Additional Observations: TCH - 159 WBL TCH - 158 EBL					

Department of Transportation and Infrastructure, Government of Newfoundland and Labrador 2026.