

		GOVERNMENT OF NEWFOUNDLAND AND LABRADOR Department of Transportation and Infrastructure		BRIDGE INSPECTION REPORT B10102024-8	
Date: 9/24/2024		Inspected By: Scott Wight		Category: Eng. - Engineering	
BRIDGE INFORMATION					
Site:		TCH-109 - TCH-RT.470 UNDERPASS ISLES AUX MORT - R			
SUBSTRUCTURE					
Condition:	G - Good	Bearings:	I - Inapplicable		
		Bearing Seat:	I - Inapplicable		
Comments:	Efflorescence noted on both abutments.				
SUPERSTRUCTURE					
Condition:	G - Good	Expansion Joints:	I - Inapplicable		
Comments:	Very minor amount of exposed rebar on the underside of deck.				
DECK					
Condition:	G - Good	Curbs:	G - Good		
Hand Rail:	G - Good	Roadway Condition:	G - Good		
Approach Rail:	F2 - Fair				
Comments:	One pothole forming in the eastbound lane. Small cracking in asphalt near approaches. Damage noted on one buried end of approach rail.				
HYDROLOGY					
Water Velocity:	0 m/s	Ice Problem:	NA - Not Applicable		
Water Depth:	0 m	Scour Problem:	NA - Not Applicable		
Waterway:	03 - Not Applicable	Debris Problem:	NA - Not Applicable		
Comments:					
REPLACEMENT/REHABILITATION					
Next Rehab. Date:		Replacement Year:			
Antic. Rehab. Cost:	\$TBD	Replacement Cost:	\$TBD		
Recommendations:					
OBSERVATIONS					
Overall Condition:	G - Good	Requires Further Inspection:	No		
Additional Observations:	No hazard markers and accumulation of winter sand along curb.				

Department of Transportation and Infrastructure, Government of Newfoundland and Labrador 2026.