

		GOVERNMENT OF NEWFOUNDLAND AND LABRADOR Department of Transportation and Infrastructure		BRIDGE INSPECTION REPORT B07292025-4	
Date: 9/24/2024		Inspected By: C.Spencer		Category: Eng. - Engineering	
BRIDGE INFORMATION					
Site:		4-188 - WATT'S BROOK BRIDGE - R			
SUBSTRUCTURE					
Condition:	P1 - Poor	Bearings:	F1 - Fair		
		Bearing Seat:	I - Inapplicable		
Comments:	Abutment walls collapsed (timber faces); Bearing seat is existing ground approx. 10' from existing abutment face location				
SUPERSTRUCTURE					
Condition:	F1 - Fair	Expansion Joints:	I - Inapplicable		
Comments:	Panels have noticable ice damage; underlying sway bracing has been damaged and stressed from ice. Corrosion on steel.				
DECK					
Condition:	P3 - Poor	Curbs:	F1 - Fair		
Hand Rail:	I - Inapplicable	Roadway Condition:	P3 - Poor		
Approach Rail:	I - Inapplicable				
Comments:	No end blocks; no approach rail; structure requires fencing or handrail. Wooden deck has areas of rotting wood. Wooden stringers missing from bridge deck/damaged.				
HYDROLOGY					
Water Velocity:	0 m/s	Ice Problem:	K - Known Problem		
Water Depth:	0 m	Scour Problem:	K - Known Problem		
Waterway:	01 - Adequate	Debris Problem:	P - Possible Problem		
Comments:					
REPLACEMENT/REHABILITATION					
Next Rehab. Date:		Replacement Year:			
Antic. Rehab. Cost:	\$0	Replacement Cost:	\$0		
Recommendations:					
OBSERVATIONS					
Overall Condition:	P1 - Poor	Requires Further Inspection:	No		
Additional Observations:	Bridge located on unmaintained road, bridge unmaintained, use at own risk.				

Department of Transportation and Infrastructure, Government of Newfoundland and Labrador 2026.