

Approach Rail:	F1 - Fair		
Comments:	- Handrail has a dent in the top - Hazard markers missing - Most posts are required for approach rails close to end blocks (at 3 corners), some bolts missing as well - Small pot holes on deck		
HYDROLOGY			
Water Velocity:	n/a m/s	Ice Problem:	NA - Not Applicable
Water Depth:	n/a m	Scour Problem:	NA - Not Applicable
Waterway:	03 - Not Applicable	Debris Problem:	NA - Not Applicable
Comments:			
REPLACEMENT/REHABILITATION			
Next Rehab. Date:	2026	Replacement Year:	2076
Antic. Rehab. Cost:	\$150	Replacement Cost:	\$4000
Recommendations:	- Small area of deck repair - Rusted bearings - Guide rail posts - Hazard markers		
OBSERVATIONS			
Overall Condition:	F2 - Fair	Requires Further Inspection:	No
Additional Observations:	Traffic control required to inspect Hazards include; tripping, slipping, falling		
LEGEND:			
Condition Definitions:		Problem Definitions:	
1 - *Good - [discontinued code].	F2 - Fair.	C - Unsafe (Closed to Public).	N - No Problem.
2 - *Fair - [discontinued code].	F1 - Fair.	U - Uninspectable.	P - Possible Problem.
3 - *Poor - [discontinued code].	P3 - Poor.	I - Inapplicable.	K - Known Problem.
4 - *Unsafe - [discontinued code].	P1 - Poor.		NA - Not Applicable.
G - Good.	P - Poor.		
Category Definitions:			
Maint. - Maintenance.			
Eng. - Engineering.			
Office - Bridge Office.			
PHOTO GUIDELINES:			
Inspection Photos:			
Please provide photos using guidelines below:			
<ul style="list-style-type: none"> ● Any item which inspector feels should be documented by photograph ● All items noted above as being P3, P1, P, or C ● Any evidence of known ice, scour, debris, waterway problems 			
INSPECTION PHOTOS			

Department of Transportation and Infrastructure, Government of Newfoundland and Labrador 2021.