19.2 m

13 **m**

0 **m**

5.1 m

 $0 \, \mathbf{m}$

Length

Length Span No.:

12.1 m



GOVERNMENT OF
NEWFOUNDLAND
AND LABRADOR
Department of Transportation and Infrastructure

BRIDGE INSPECTION REPORT B10042021-7

Overall Length:

Overall Width:

Roadway Width:

Sidewalk Width:

N.W.L.:

Spans:

Span No.:

Clearance to R.D. or

Max Depth of N.W.L.:

Date: 10/3/2021 Inspected By: Justine Geddes Category: Office - Bridge Office

BRIDGE INFORMATION

Site: TCH-187 - GROVES ROAD OVERPASS WEST

Route: 1

Year Built: 1998 Est: No
Year Last Rehab.: Est: No

Region: AVALON PENINSULA

Jurisdiction: Provincial

Type of Structure: 03 - Reinforced Concrete Beam/Slab

Purpose of Structure: 01 - Highway Grade Separation

Type of Handrail: 05 - Concrete Barrier

02 - Asphalt Roadway Surface: 1 14 4 01 - Good 2 0 5 0 Alignment Vertical: 01 - Good 3 0 6 0 Alignment Horizontal:

Restrictions: No

BRIDGE PHOTOS





SUBSTRUCTURE

Condition: F2 - Fair **Bearings:** F1 - Fair

Bearing Seat: F2 - Fair

Comments: - Bearings likely undersized

SUPERSTRUCTURE

Condition: F2 - Fair **Expansion Joints:** F1 - Fair

Comments: - No signs of leaking expansion joints

DECK

Condition: F1 - Fair Curbs: I - Inapplicable

Hand Rail: F2 - Fair Roadway Condition: I - Inapplicable

1			
Approach Rail:	F2 - Fair		
Comments:	- Sand/debris beside handrail - Sealant at barrier joints starting to go - No visible potholes but asphalt looks like its rotting, especially at approach slabs		
HYDROLOGY			
Water Velocity:	n/a m/s	Ice Problem:	NA - Not Applicable
Water Depth:	n/a m	Scour Problem:	NA - Not Applicable
Waterway:	03 - Not Applicable	Debris Problem:	NA - Not Applicable
Comments:			
REPLACEMENT/REHABILITATION			
Next Rehab. Date:	2031	Replacement Year	r: 2073
Antic. Rehab. Cost:	\$100	Replacement Cos	t: \$4000
Recommendations:	- May need repairing earlier than 2031 - 2 missing hazard markers		
OBSERVATIONS			
Overall Condition:	F2 - Fair	Requires Further Inspection:	No
Additional Observations:	- Traffic control required for inspection - Hazards; slipping, tripping, falling		
LEGEND: Condition Definitions: 1-*Good - [discontinued code]. 2-*Fair - [discontinued code]. 3-*Poor - [discontinued code]. 4-*Unsafe - [discontinued code]. G - Good. PHOTO GUIDELINES: Inspection Photos: Please provide photos using guideling any item which inspector and the provide photos of Any evidence of known ice	F2 - Fair. C - Unsafe (Closed to F1 - Fair. U - Uninspectable. P3 - Poor. I - Inapplicable. P1 - Poor. P - Poor. P - Poor. tes below: eets should be documented by pnotograpn eets should be of the poor. The poor is a commented by pnotograpn eets should be documented by pnotograpn	Public).	Problem Definitions: N - No Problem. P - Possible Problem. K - Known Problem. NA - Not Applicable. Category Definitions: Maint Maintenance. Eng Engineering. Office - Bridge Office.
INSPECTION PHOTOS			

Department of Transportation and Infrastructure, Government of Newfoundland and Labrador 2021.