34.2 m



GOVERNMENT OF
NEWFOUNDLAND
AND LABRADOR
Department of Transportation and Infrastructure

BRIDGE INSPECTION REPORT B06302021-7

Date: 1/29/2020 Inspected By: Hunt R Category: Eng. - Engineering

BRIDGE INFORMATION

Site: 1-011 - LAMANCHE RIVER BRIDGE, CAPE BROYLE

Route: Overall Length:

Year Built:1965Est: YesOverall Width:9.1 mYear Last Rehab.:1980Est: YesRoadway Width:6.2 m

Region: AVALON PENINSULA Sidewalk Width: 0 m

Jurisdiction: Provincial Clearance to R.D. or N.W.L.:

Type of Structure: 02 - Double Tee Max Depth of N.W.L.: 0 m

Purpose of Structure: 04 - Over Non-Navigable Waters Spans:

01 - Aluminum Rail Type of Handrail: Span No.: Length Span No.: Length 02 - Asphalt Roadway Surface: 1 15.4 4 01 - Good 2 0 5 0 Alignment Vertical: 01 - Good 3 0 6 0 Alignment Horizontal:

Restrictions: No

BRIDGE PHOTOS





SUBSTRUCTURE

Condition: G - Good **Bearings**: G - Good

Bearing Seat: G - Good

Comments: Some narrow vertical cracks on faces of abutments and ballast walls

SUPERSTRUCTURE

Condition: G - Good Expansion Joints: G - Good

Comments: CPCI 1900 girders. Semi-integral abutment with WABO Inverseal Expansion

DECK

Condition: G - Good Curbs: I - Inapplicable

Hand Rail: G - Good Roadway Condition: I - Inapplicable

| Approach Rail: | G - Good | | |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------|
| Comments: | North west hazard marker missing. Some narrow vertical cracks in barrier walls. | | |
| HYDROLOGY | | | |
| Water Velocity: | 0.3 m/s | Ice Problem: | P - Possible Problem |
| Water Depth: | 0.6 m | Scour Problem: | N - No Problem |
| Waterway: | 01 - Adequate | Debris Problem: | N - No Problem |
| Comments: | ' | | |
| REPLACEMENT/REHAB | ILITATION | | |
| Next Rehab. Date: | 2054 | Replacement Year: | 2092 |
| Antic. Rehab. Cost: | \$100000 | Replacement Cost: | \$500000 |
| Recommendations: | replace missing hazard marker (Maintenance) | | |
| OBSERVATIONS | | | |
| Overall Condition: | G - Good | Requires Further Inspection: | No |
| Additional Observations: | Same as previous inspection in 2018 | | |
| LEGEND: Condition Definitions: 1 - *Good - [discontinued code]. 2 - *Fair - [discontinued code]. 3 - *Poor - [discontinued code]. 4 - *Unsafe - [discontinued code]. G - Good. PHOTO GUIDELINES: Inspection Photos: Please provide photos using guidelir Any item which inspector - All Items noted above as beautiful and the provide and the provide and the photos and the provide and the photos and th | F2 - Fair. C - Unsafe (C - F1 - Fair. U - Uninspec P3 - Poor. I - Inapplicab P1 - Poor. P - Poor. P - Poor. P - Poor. P - Poor. | Closed to Public). N - No table. P - Pos le. K - Kno | m <u>Definitions:</u> Problem. Sible Problem. Sible Problem. Sing - Engineering. Swn Problem. Office - Bridge Office. Office - Bridge Office. |
| INSPECTION PHOTOS | | | |

 $Department of \ Transportation \ and \ Infrastructure, \ Government \ of \ Newfoundland \ and \ Labrador \ 2021.$