

GOVERNMENT OF
NEWFOUNDLAND
AND LABRADOR
Department of Transportation and Infrastructure

BRIDGE INSPECTION REPORT B10282015-13

Date: 9/23/2015 Inspected By: Rodger Hussey Category: Eng. - Engineering

BRIDGE INFORMATION

Site: TCH-104 - PADDY'S POND UNDERPASS

Route: 1

Year Built: 1984 Est: No
Year Last Rehab.: Est: No

Region: AVALON PENINSULA

Jurisdiction: Provincial

Type of Structure: 04 - Rigid Frame

Purpose of Structure: 01 - Highway Grade Separation

01 - Good

Type of Handrail: 01 - Aluminum Rail

Roadway Surface: 02 - Asphalt

Alignment Vertical: 01 - Good

Restrictions: No

Overall Length: 34.5 m

Overall Width: 9.9 m Roadway Width: 8 m

Sidewalk Width: 0.95 m

Clearance to R.D. or

N.W.L.:

Max Depth of N.W.L.: 0 m

Spans:

 Span No.:
 Length
 Span No.:
 Length

 1
 16.2
 4
 0

 2
 0
 5
 0

 3
 0
 6
 0

5 **m**

BRIDGE PHOTOS

Alignment Horizontal:





SUBSTRUCTURE

Condition: F2 - Fair **Bearings:** I - Inapplicable

Bearing Seat: I - Inapplicable

Comments: Moderate spalling along the top of westbound wingwall; Minor cracking throughout abutment walls and headwalls.

SUPERSTRUCTURE

Condition: G - Good Expansion Joints: I - Inapplicable

Comments:

DECK

Condition: F2 - Fair Curbs: F2 - Fair

Hand Rail: F2 - Fair **Roadway Condition:** F2 - Fair

Annuach Deile	P3 - Poor		
Approach Rail:			
Comments:	Approach rail has become detached from end block.		
HYDROLOGY			
Water Velocity:	0 m/s	Ice Problem:	NA - Not Applicable
Water Depth:	0 m	Scour Problem:	NA - Not Applicable
Waterway:	03 - Not Applicable	Debris Problem:	NA - Not Applicable
Comments:			
REPLACEMENT/REHAB	ILITATION		
Next Rehab. Date:	2015	Replacement Year:	2015
Antic. Rehab. Cost:	\$0	Replacement Cost:	\$0
Recommendations:	Attach approach rail to end block.		
OBSERVATIONS			
Overall Condition:	F2 - Fair	Requires Further Inspection:	No
Additional Observations:			
LEGEND: Condition Definitions: 1 - *Good - [discontinued code]. 2 - *Fair - [discontinued code]. 3 - *Poor - [discontinued code]. 4 - *Unsafe - [discontinued code]. G - Good. PHOTO GUIDELINES: Inspection Photos: Please provide photos using guidelir All tems noted above as b All tems noted above as b Any evidence of known ice	F2 - Fair. C - Unsafe (Closed to F1 - Fair. U - Uninspectable. P3 - Poor. I - Inapplicable. P1 - Poor. P - Poor. nes below: eels should be documented by photograph eing P3. P1. P. or C, scour, debris, waterway problems	Public). N - No P P - Poss K - Knov	Definitions: roblem. Maint Maintenance. ible Problem. Eng Englineering. vn Problem. Office - Bridge Office. Applicable.
INSPECTION PHOTOS			

Department of Transportation and Infrastructure, Government of Newfoundland and Labrador 2021.