

Highway Inspection Reporting

Government of Newfoundland and Labrador - Canada

[Government Home](#)

[Search](#)

[Sitemap](#)

[Contact Us](#)



Recommended: Please use custom **Back** buttons where applicable.

Welcome to the Highway Design Bridge Inspection Report form. Please read the instructions at the end of this form before filling out the form. Click on the [Help](#) button to view the instructions

[Back](#) **INSPECTION REPORT** **No.B07232018-16** [Print](#) [Help ?](#)

Date: Inspected By: [Add](#) Category: [v](#)

[Details](#) **Select Structure:** [v](#)

▲ Click to view structure Information

[Select](#) [Edit](#) [Add](#)

Bridge Name:	<input type="text" value="1-314 - PENSTOCK BRIDGE, SEAL COVE"/>				
Region:	<input type="text" value="AVALON PENINSULA"/>	Overall Length:	<input type="text" value="8.7"/> m		
Route:	<input type="text"/>	Overall Width:	<input type="text" value="11.1"/> m		
Year Built:	<input type="text" value="1955"/> Est: <input type="checkbox"/>	Roadway Width:	<input type="text" value="10.6"/> m		
Year Last Rehab.:	<input type="text"/> Est: <input type="checkbox"/>	Sidewalk Width:	<input type="text" value="0"/> m		
Jurisdiction:	<input type="text" value="Provincial"/>	Clearance to R.D. or N.W.L.:	<input type="text" value="2.7"/> m		
Type of Structure:	<input type="text" value="13 - Other"/>	Max Depth of N.W.L.:	<input type="text" value="0"/> m		
Purpose of Structure:	<input type="text" value="04 - Over Non-Navigable Waters"/>	Spans:			
Type of Handrail:	<input type="text" value="02 - Concrete Rail"/>	Span No.:	Length of Span		
Roadway Surface:	<input type="text" value="02 - Asphalt"/>	1	<input type="text" value="4.7"/> m		
Alignment Vertical:	<input type="text" value="02 - Adequate"/>	2	<input type="text" value="0"/> m		
Alignment Horiz.:	<input type="text" value="02 - Adequate"/>	3	<input type="text" value="0"/> m		
Restrictions:	<input type="text" value="No"/>	4	<input type="text" value="0"/> m		
Describe Restrictions:	<div style="border: 1px solid black; height: 60px;"></div>				
				5	<input type="text" value="0"/> m
				6	<input type="text" value="0"/> m

[Click here for photos ►](#) [Structure Photos](#)

Substructure

Condition:
 Bearings:
 Bearing Seat:

Insp. Comments:

Click to expand/collapse comments ▼ ▲

Superstructure

Condition:
 Expansion Joints:

Insp. Comments:

Click to expand/collapse comments ▼ ▲

Deck/Approach

Condition:
 Hand Rail Condition:
 Approach Rail Condition:
 Curb Condition:
 Roadway Condition:

Insp. Comments:

Click to expand/collapse comments ▼ ▲

Hydrology

Water Velocity: m/s
 Waterway:
 Water Depth: m
 Ice Problem:
 Scour Problem:
 Debris Problem:

Insp. Comments:

Click to expand/collapse comments ▼ ▲

Replacement/Rehab

Next Rehab. Yr: Replacement Year:

Ant. Rehab. Cst: Replacement Cost:

Recomm:

Click to expand/collapse comments ▼ ▲

Observations

Overall Condition: Req. Further Inspection.:

Additional Observ.:

Click to expand/collapse comments ▼ ▲

Click here for photos ►

FOR OFFICE USE ONLY

Design Office Comments:

Click to expand/collapse comments ▼ ▲

Instructions

Please **Log Out** of the Highway Design Inspection Administration website when you have finished. To log off click on the log out key below.

*Recommended: Please use custom **Back** buttons where applicable.

Revised: Monday,

September 20, 2021

[Administration Menu](#)

Users online:16

[Log out](#) 

[Version 2.32](#)



[Home](#)

[Back to Government](#)

[Back to Department](#)

[Site Map](#)

[Contact Us](#)



All material copyright the Government of Newfoundland and Labrador. No unauthorized copying or redeployment permitted. The Government assumes no responsibility for the accuracy of any material deployed on an unauthorized server.