

GOVERNMENT OF
NEWFOUNDLAND
AND LABRADOR
Department of Transportation and Infrastructure

BRIDGE INSPECTION REPORT B07202021-7

Date: 7/8/2021 Inspected By: McCaw J Category: Eng. - Engineering **BRIDGE INFORMATION** Site: 3-108 - BADGER BROOK PEDESTRIAN BRIDGE Route: 0 m **Overall Length:** 1991 Year Built: Est: No **Overall Width:** $0 \, \mathbf{m}$ Year Last Rehab.: Est: No Roadway Width: $0 \, \mathbf{m}$ Region: **CENTRAL WEST** Sidewalk Width: $0 \, \mathbf{m}$ Clearance to R.D. or Jurisdiction: Provincial 0 **m** N.W.L.: Type of Structure: 13 - Other Max Depth of N.W.L.: $0 \, \mathbf{m}$ Purpose of Structure: 04 - Over Non-Navigable Waters Spans: 03 - Timber Rail Type of Handrail: Span No.: Length Span No.: Length 03 - Timber Roadway Surface: 1 0 4 01 - Good 2 0 5 0 Alignment Vertical: 3 0 6 0 01 - Good Alignment Horizontal: No Restrictions: **BRIDGE PHOTOS SUBSTRUCTURE** Condition: P3 - Poor Bearings: G - Good **Bearing Seat:** P3 - Poor Comments: Spalling extensive and covers nearly all concrete surfaces. **SUPERSTRUCTURE** G - Good Condition: **Expansion Joints:** I - Inapplicable Comments: **DECK** P3 - Poor P3 - Poor Condition: Curbs: P3 - Poor Hand Rail: P3 - Poor **Roadway Condition:** I - Inapplicable Approach Rail: Rotting deck timbers. Diagonal braces missing from several handrail posts. Comments: **HYDROLOGY** N - No Problem $0.1 \, \text{m/s}$ Water Velocity: Ice Problem: Water Depth: 1.0 **m** Scour Problem: N - No Problem N - No Problem 01 - Adequate **Debris Problem:** Waterway: Comments:

REPLACEMENT/REHABILITATION					
Next Rehab. Date:	2024	R	eplacement Year:	2021	
Antic. Rehab. Cost:	\$30000	R	eplacement Cost:	\$0	
Recommendations:	Replace rotting timbers and missing diagonals.				
OBSERVATIONS					
Overall Condition:	P3 - Poor		equires Further	No	
Additional Observations: P3 - Timber Deck and abutments. F2 - Remainder. Parking ok. hazards:water, slipping					
LEGEND: Condition Definitions: 1 - "Good - [discontinued code]. 2 - *Fair - [discontinued code]. 3 - *Poor - [discontinued code]. 4 - *Unsafe - [discontinued code]. G - Good. PHOTO GUIDELINES: Inspection Photos: Please provide photos using guideli Any item which inspector All items noted above as to Any evidence of known ice	F2 - Fair. F1 - Fair. P3 - Poor. P1 - Poor. P - Poor. P - Poor. reeis snouig pe gocumented by peing P3, P1, P or Ceeps course.	C - Unsafe (Closed to Pul U - Uninspectable. I - Inapplicable. notograpn	olic). N - N P - F K - P	olem Definitions: No Problem. Yossible Problem. Known Problem. Not Applicable.	Category Definitions: Maint - Maintenance. Eng Engineering. Office - Bridge Office.
INSPECTION PHOTOS					

Department of Transportation and Infrastructure, Government of Newfoundland and Labrador 2021.