18.5 m

0 **m** 



GOVERNMENT OF **NEWFOUNDLAND** AND LABRADOR Department of Transportation and Infrastructure

## BRIDGE INSPECTION REPORT B07162021-5

**Overall Length:** 

Date: 7/9/2021 Inspected By: McCaw J Category: Eng. - Engineering

**BRIDGE INFORMATION** 

Site: TCH-172 - JUMPER'S BROOK BRIDGE

Route:

1967 Year Built: Est: No **Overall Width:**  $0 \, \mathbf{m}$ Year Last Rehab.: Est: No Roadway Width: 7 m 0 m

Region: **CENTRAL WEST** Sidewalk Width:

Clearance to R.D. or Jurisdiction: Provincial N.W.L.:

Type of Structure: 02 - Double Tee Max Depth of N.W.L.:  $0 \, \mathbf{m}$ 

04 - Over Non-Navigable Waters Purpose of Structure: Spans:

02 - Concrete Rail Type of Handrail: Span No.: Length Span No.: Length 02 - Asphalt Roadway Surface: 1 12.4 4 01 - Good 2 0 5 0 Alignment Vertical: 01 - Good 3 0 6 0 Alignment Horizontal:

No Restrictions:

**BRIDGE PHOTOS** 

**SUBSTRUCTURE** 

Condition: F2 - Fair Bearings: I - Inapplicable

> **Bearing Seat:** I - Inapplicable

Comments: Vertical cracks along both abutments. Spalling at abutment corners/. Erosion at ends of wingwalls.

**SUPERSTRUCTURE** 

P3 - Poor Condition: **Expansion Joints:** U - Uninspectable

Expansion joints paved over. Pre-stressing exposed in multiple locations. Cracking visible on several girders. Comments:

**DECK** 

F2 - Fair F2 - Fair Condition: Curbs:

Hand Rail: G - Good F2 - Fair **Roadway Condition:** 

F2 - Fair Approach Rail:

Deck leaking at multiple locations. Some cracking at expansion joint locations. No potholes on deck. Comments:

**HYDROLOGY** 

N - No Problem 0.3 m/s Water Velocity: Ice Problem: Water Depth: 0.3 **m** Scour Problem: N - No Problem N - No Problem

01 - Adequate **Debris Problem:** Waterway:

Comments:

REPLACEMENT/REHABILITATION					
Next Rehab. Date:	2025	Replacem	ent Year:	2025	
Antic. Rehab. Cost:	\$150000	Replacem	ent Cost:	\$3000000	
Recommendations:					
OBSERVATIONS					
Overall Condition:	F1 - Fair	Requires Inspection		No	
Additional Observations: Need to monitor double tee-deterioration. Parking ok. Hazards: Traffic, Slipping, Water					
LEGEND: Condition Definitions:  1 - *Good - (discontinued code). 2 - *Fair - (discontinued code). 3 - *Poor - [discontinued code]. 4 - *Unsafe - [discontinued code]. G - Good. PHOTO GUIDELINES: Inspection Photos: Please provide photos using guidelity and the provide photos using guidelity and guidelity	F2 - Fair. F1 - Fair. P3 - Poor. P1 - Poor. P - Poor. P - Poor. reeis snou ne documented by pneing P3 P1 P. or C. e, scour, debris, waterway problem	C - Unsafe (Closed to Public). U - Uninspectable. I - Inapplicable. otograpn	Problem D. N - No Prok P - Possibl K - Known NA - Not A <sub>l</sub>	olem. e Problem. Problem.	Category Definitions: Maint Maintenance. Eng Engineering. Office - Bridge Office.
INSPECTION PHOTOS					

Department of Transportation and Infrastructure, Government of Newfoundland and Labrador 2021.