Newfoundland Labrador	GOVERNMENT OF NEWFOUNDLAND AND LABRADOR Department of Transportation and Infrastructure		BRIDGE INSPECTION REPORT B07222021-2					
Date: 7/8/2021	Inspected By: McCa		Category: Eng Engineering					
BRIDGE INFORMATION								
Site:	TCH-042 - LEECH BRO	OOK BRIDGE (TH	UNDER BROOK)					
Route:				Overall Leng	gth:	41 m		
Year Built:	1965	Est: No		Overall Wid		9.9 m		
Year Last Rehab.:	1998	Est: No		Roadway W		8.3 m		
Region:	CENTRAL WEST			Sidewalk W		0 m		
Jurisdiction:	Provincial			Clearance to R.D. or 2.9 m N.W.L.:				
Type of Structure:	01 - AASH to Girder			Max Depth of N.W.L.:		1 m		
Purpose of Structure:	04 - Over Non-Navigable Waters			Spans:				
Type of Handrail:	01 - Aluminum Rail			Span No.:	<u>Length</u>	Span No.:	<u>Length</u>	
Roadway Surface:	02 - Asphalt			1	28.7	4	0	
Alignment Vertical:	01 - Good			2	0	5	0	
Alignment Horizontal:	01 - Good			3	0	6	0	
Restrictions:	No							
BRIDGE PHOTOS								
SUBSTRUCTURE								
Condition:	F2 - Fair		Bearings:	F2 -	Fair			
			Bearing Seat:	F2 - I	Fair			
Comments:	Spalling at bearing seat. Joints leaking on abutments.							
SUPERSTRUCTURE								
Condition:	F2 - Fair Expansion Joint			s: P3 - Poor				
Comments:	Some girder rusting and spalling on diaphrams							
DECK								
Condition:	F1 - Fair		Curbs:	P3 -	Poor			
Hand Rail:	F2 - Fair		Roadway Conditior	n: P3 -	Poor			
Approach Rail:	F2 - Fair							
Comments:	Deck leaking in multiple	e locations. End bl	ocks spalling and crack	king. Curbs sp	alling and	potholes in de	ck.	
HYDROLOGY								
Water Velocity:	0.1 m/s		Ice Problem:	N - N	lo Problem			
Water Depth:	0.3 m		Scour Problem:	Problem: N - No Problem				
Waterway:	01 - Adequate		Debris Problem:	N - N	lo Problem			
Comments:								

REPLACEMENT/REHABILITATION										
Next Rehab. Date:	2025		Replacement Yea	r: 202	1					
Antic. Rehab. Cost:	\$150000		Replacement Cos	st: \$40	00000					
Recommendations:	Repair diaphragms, girders, deck and curbs. Patch potholes									
OBSERVATIONS										
Overall Condition:	F2 - Fair		Requires Further Inspection:	No						
Additional Observations: Parking ok. Hazards: Traffic, Slipping, Water										
LEGEND: Condition Definitions: 1 - *Good - [discontinued code]. 2 - *Fair - [discontinued code]. 3 - *Poor - [discontinued code]. 4 - *Unsafe - [discontinued code]. G - Good. PHOTO GUIDELINES: Inspection Photos: Please provide photos using guidelir Please provide photos using guidelir — Any rem which upspector — Any evidence of known ice	F2 - Fair. F1 - Fair. P3 - Poor. P1 - Poor. P - Poor. ens below: eng P3, P1 P or C scour, debris, waterway problem	C - Unsafe (Closed to U - Uninspectable. I - Inapplicable. notograpn	Public).	Problem Definition N - No Problem. P - Possible Probl K - Known Problen NA - Not Applicab	em. n.	Category Definitions: Maint Maintenance. Eng Engineering. Office - Bridge Office.				
INSPECTION PHOTOS										

Department of Transportation and Infrastructure, Government of Newfoundland and Labrador 2021.