

Date: 1/13/2020

GOVERNMENT OF **NEWFOUNDLAND** AND LABRADOR Department of Transportation and Infrastructure

Inspected By: Lynch R / Martin L

BRIDGE INSPECTION REPORT B01132020-21

Category: Eng. - Engineering

BRIDGE INFORMATION Site: TCH-044 - LITTLE JUNCTION BROOK BRIDGE Route: 0 m **Overall Length:** 1964 Year Built: Est: Yes **Overall Width:** $0 \, \mathbf{m}$ Year Last Rehab.: Est: No Roadway Width: $0 \, \mathbf{m}$ Region: **CENTRAL WEST** Sidewalk Width: $0 \, \mathbf{m}$ Clearance to R.D. or Jurisdiction: Provincial 0 **m** N.W.L.: Type of Structure: 13 - Other Max Depth of N.W.L.: $0 \, \mathbf{m}$ Purpose of Structure: 04 - Over Non-Navigable Waters Spans: 06 - None Type of Handrail: Span No.: Length Span No.: Length 02 - Asphalt Roadway Surface: 1 0 4 02 - Adequate 2 0 5 0 Alignment Vertical: 3 0 6 0 02 - Adequate Alignment Horizontal: No Restrictions: **BRIDGE PHOTOS SUBSTRUCTURE** Condition: F2 - Fair Bearings: I - Inapplicable **Bearing Seat:** I - Inapplicable Comments: Footing undermined on LHS (downstream). Rebar exposed in wing walls on LHS **SUPERSTRUCTURE** F2 - Fair Condition: **Expansion Joints:** I - Inapplicable Comments: Rigid concrete box culvert on footings (bottomless) **DECK** F2 - Fair I - Inapplicable Condition: Curbs: Hand Rail: I - Inapplicable I - Inapplicable

HYDROLOGY Water Velocity:

Approach Rail:

Comments:

0 m/s

F2 - Fair

Ice Problem:

N - No Problem

Water Depth: 0 m

Scour Problem:

Roadway Condition:

K - Known Problem

Waterway: 01 - Adequate **Debris Problem:**

K - Known Problem

Comments:

Large boulders on RHS, large washout on RHS in shoulder.

Newer asphalt on road surface.

REPLACEMENT/REHABILITATION				
Next Rehab. Date:		Replacen	Replacement Year:	
Antic. Rehab. Cost:	\$0	Replacem	nent Cost: \$0	
Recommendations:	Repair washout on RHS of crossing. Repair disintegrated ends of structure and install guide rail.			
OBSERVATIONS				
Overall Condition:	F2 - Fair	Requires Inspectio		
Additional Observations: Rigid concrete box culvert on footings (bottomless)				
LEGEND: Condition Definitions: 1 - *Good - [discontinued code]. 2 - *Fair - [discontinued code]. 3 - *Poor - [discontinued code]. 4 - *Unsafe - [discontinued code]. G - Good. PHOTO GUIDELINES: Inspection Photos:	F2 - Fair. F1 - Fair. P3 - Poor. P1 - Poor. P - Poor.	C - Unsafe (Closed to Public). U - Uninspectable. I - Inapplicable.	Problem Definitions: N - No Problem. P - Possible Problem. K - Known Problem. NA - Not Applicable.	Category Definitions: Maint Maintenance. Eng Engineering. Office - Bridge Office.
Please provide photos using guideli Any nem wnich inspector All items noted above as because Any evidence of known ice	nes pelow: reels snoula pe documented by p leing P3, P1, P, or C e, scour, debris, waterway proble	onotograpn ms		
INSPECTION PHOTOS				

Department of Transportation and Infrastructure, Government of Newfoundland and Labrador 2021.