

	GOVERNMENT OF NEWFOUNDLAND AND LABRADOR Department of Transportation and Infrastructure	<b>BRIDGE INSPECTION REPORT</b> <b>B12022005-4</b>	
<b>Date:</b> 11/21/2005	<b>Inspected By:</b> Kendell C	<b>Category:</b> Eng. - Engineering	
<b>BRIDGE INFORMATION</b>			
<b>Site:</b>	3-168 - PILLEY'S ISLAND BRIDGE		
<b>Route:</b>		<b>Overall Length:</b>	8 m
<b>Year Built:</b>	<b>Est:</b> No	<b>Overall Width:</b>	4 m
<b>Year Last Rehab.:</b>	<b>Est:</b> No	<b>Roadway Width:</b>	4 m
<b>Region:</b>	CENTRAL WEST	<b>Sidewalk Width:</b>	0 m
<b>Jurisdiction:</b>	Municipal	<b>Clearance to R.D. or N.W.L.:</b>	0 m
<b>Type of Structure:</b>	04 - Rigid Frame	<b>Max Depth of N.W.L.:</b>	0 m
<b>Purpose of Structure:</b>	04 - Over Non-Navigable Waters	<b>Spans:</b>	
<b>Type of Handrail:</b>	03 - Timber Rail	<u>Span No.:</u>	<u>Length</u>
<b>Roadway Surface:</b>	01 - Concrete	<u>Span No.:</u>	<u>Length</u>
<b>Alignment Vertical:</b>	02 - Adequate	1	6.8
<b>Alignment Horizontal:</b>	02 - Adequate	2	0
<b>Restrictions:</b>	Yes	3	0
<b>Describe Restrictions:</b>	One Lane	4	0
		5	0
		6	0
<b>BRIDGE PHOTOS</b>			
			
<b>SUBSTRUCTURE</b>			
<b>Condition:</b>	G - Good	<b>Bearings:</b>	I - Inapplicable
		<b>Bearing Seat:</b>	I - Inapplicable
<b>Comments:</b>			
<b>SUPERSTRUCTURE</b>			
<b>Condition:</b>	G - Good	<b>Expansion Joints:</b>	I - Inapplicable
<b>Comments:</b>	One lane structure		
<b>DECK</b>			
<b>Condition:</b>	F2 - Fair	<b>Curbs:</b>	I - Inapplicable
<b>Hand Rail:</b>	F2 - Fair	<b>Roadway Condition:</b>	I - Inapplicable



**Description:**  
fishtail

rotten post NE corner

Department of Transportation and Infrastructure, Government of Newfoundland and Labrador 2021.