Newfoundland Labrador	GOVERNMENT OF NEWFOUNDLAND AND LABRADOR Department of Transportation and Infrastructure		BRII	BRIDGE INSPECTION REPORT B07162021-9 Category: Eng Engineering				
Date: 7/9/2021	Inspected By: McCa							
BRIDGE INFORMATION								
Site:	3-080 - RATTLING BR	OOK BRIDGE #OI	NE					
Route:	351			Overall Leng	gth:	21.7 m		
Year Built:	1955	Est: No		Overall Wid	:h:	9.8 m		
Year Last Rehab.:		Est: No		Roadway W	idth:	8.5 m		
Region:	CENTRAL WEST			Sidewalk W	dth:	0 m		
Jurisdiction:	Provincial		Clearance to R.D. or N.W.L.:		6 m			
Type of Structure:	04 - Rigid Frame			Max Depth of	Max Depth of N.W.L.:		1 m	
Purpose of Structure:	04 - Over Non-Navigat	le Waters		Spans:				
Type of Handrail:	02 - Concrete Rail			Span No.:	<u>Length</u>	Span No.:	Length	
Roadway Surface:	02 - Asphalt			1	18.4	4	0	
Alignment Vertical:	01 - Good			2	0	5	0	
Alignment Horizontal:	01 - Good			3	0	6	0	
Restrictions:	No							
BRIDGE PHOTOS								
SUBSTRUCTURE								
Condition:	F1 - Fair		Bearings:	I - Ina	I - Inapplicable			
			Bearing Seat:	l - Ina	applicable			
Comments:	Some cracking and efflor on abutments. Wingwalls have cracking, spalling, and efflorescence Significant horizontal gap at footing/abutment joint.							
SUPERSTRUCTURE								
Condition:	F2 - Fair		Expansion Joints	s: I - Ina	applicable			
Comments:	Efflorescence coming	out of deck. Cracki	ng and spalling on u	nderside of decl	along cen	terline of road	lway.	
DECK								
Condition:	F2 - Fair		Curbs:	F2 - Fair				
Hand Rail:	G - Good		Roadway Conditi	i on: F2 - I	air			
Approach Rail:	F2 - Fair							
Арргоасті кап.	Potholos on surfaco. (cracking at edges o	of frame.					
	Foundies on surface. C							
Comments:								
Comments: HYDROLOGY	2.0 m/s		Ice Problem:	N - N	o Problem			
Approach Rail. Comments: HYDROLOGY Water Velocity: Water Depth:			Ice Problem: Scour Problem:		o Problem o Problem			

Comments:							
REPLACEMENT/REHAB	ILITATION						
Next Rehab. Date:	2027	Replacement Year:	2045				
Antic. Rehab. Cost:	\$150000	Replacement Cost	\$300000				
Recommendations:	Install steel handrail and new guiderail. Remove asphalt and repair deck. Patch holes/cracks in abutments.						
OBSERVATIONS							
Overall Condition:	F2 - Fair	Requires Further Inspection:	No				
Additional Observations:	Hydro dam located upstream. Parking ok. Hazards: traffic, slipping, water						
LEGEND: Condition Definitions: 1 • 'Good - [discontinued code]. 2 • 'Fair - [discontinued code]. 3 • 'Poor - [discontinued code]. 4 • 'Unsafe - [discontinued code]. G - Good. PHOTO GUIDELINES: Inspection Photos: Please provide photos using guidelir Please provide photos using guidelir All items noted above as b Any evidence of known ice INSPECTION PHOTOS	F1 - Fair. U - Un	afe (Closed to Public). Normality (Closed to Public). Policable. Policable. K	Problem Definitions: I - No Problem. - Possible Problem. C - Known Problem. A - Not Applicable. C - Known Problem. C - K				

Department of Transportation and Infrastructure, Government of Newfoundland and Labrador 2021.