Newfoundland Labrador	GOVERNMENT OF NEWFOUNDLAN AND LABRADOR Department of Transportation	t	BRIDGE INSPECTION REPORT B07162021-11 Category: Eng Engineering					
Date: 7/8/2021	Inspected By: McCa	w J						
BRIDGE INFORMATION	ı							
Site:	3-109 - RED CLIFF RO	AD BRIDGE						
Route:				Overall Leng	gth:	11 m		
Year Built:	1965	Est: Yes		Overall Width:		7 m		
Year Last Rehab.:	1999	Est: No		Roadway Width:		6.2 m		
Region:	CENTRAL WEST			Sidewalk Wi	idth:	0 m		
Jurisdiction:	Provincial			Clearance to N.W.L.:	o R.D. or	1.4 m		
Type of Structure:	03 - Reinforced Concre	te Beam/Slab		Max Depth o	of N.W.L.:	0.3 m		
Purpose of Structure:	04 - Over Non-Navigab	le Waters		Spans:				
Type of Handrail:	06 - None			Span No.:	<u>Length</u>	Span No.:	<u>Length</u>	
Roadway Surface:	02 - Asphalt			1	6.1	4	0	
Alignment Vertical:	02 - Adequate			2	0	5	0	
Alignment Horizontal:	02 - Adequate			3	0	6	0	
Restrictions:	No							
BRIDGE PHOTOS								
SUBSTRUCTURE								
Condition:	F1 - Fair		Bearings:	I - Inapplicable				
			Bearing Seat:	F1 - F	Fair			
Comments:	Wide cracks in abutme	nt and wingwalls.						
SUPERSTRUCTURE								
SUPERSTRUCTURE	P3 - Poor		Expansion Joints:	l - Ina	applicable			
Condition:	P3 - Poor Spalling concrete on or				••			
Condition: Comments:					••			
Condition: Comments: DECK					ghout			
Condition: Comments: DECK Condition:	Spalling concrete on or		rebar exposed. Minor	cracking throu P3 - I	ghout Poor			
Condition: Comments: DECK Condition: Hand Rail:	Spalling concrete on ou F1 - Fair		rebar exposed. Minor Curbs:	cracking throu P3 - I	ghout Poor			
Condition: Comments: DECK Condition: Hand Rail: Approach Rail:	Spalling concrete on ou F1 - Fair I - Inapplicable	utside girders with	rebar exposed. Minor Curbs: Roadway Conditio	P3 - I n: P3 - I	ghout Poor Poor	ning. No haza	ard market	
Condition: Comments: DECK Condition: Hand Rail: Approach Rail: Comments:	Spalling concrete on ou F1 - Fair I - Inapplicable P3 - Poor Approach rail damaged	utside girders with	rebar exposed. Minor Curbs: Roadway Conditio	P3 - I n: P3 - I	ghout Poor Poor	ning. No haza	ard marke	
Condition: Comments: DECK Condition: Hand Rail: Approach Rail: Comments: HYDROLOGY	Spalling concrete on ou F1 - Fair I - Inapplicable P3 - Poor Approach rail damaged	utside girders with	rebar exposed. Minor Curbs: Roadway Conditio	P3 - I n: P3 - I ng. Curbs (tim	ghout Poor Poor	ning. No haza	ard marke	
	Spalling concrete on ou F1 - Fair I - Inapplicable P3 - Poor Approach rail damaged present.	utside girders with	rebar exposed. Minor Curbs: Roadway Conditio patches. Deck is leaki	P3 - I P3 - I n: P3 - I ng. Curbs (tim	ghout Poor Poor ber) are lea	ning. No haza	ard marke	

Comments:								
REPLACEMENT/REHAB	ILITATION							
Next Rehab. Date:	2030			Replacement Yea	ır:	2040		
Antic. Rehab. Cost:	\$50000			Replacement Cos	st:	\$1000000		
Recommendations:	Appears to	be a non-ma	aintained structure					
OBSERVATIONS								
Overall Condition:	F1 - Fair			Requires Further Inspection:		No		
Additional Observations:	Parking ok.	Hazards: tra	affic, slipping, wate	r				
LEGEND: Condition Definitions: 1 - *Good - [discontinued code]. 2 - *Fair - [discontinued code]. 3 - *Poor - [discontinued code]. 4 - *Unsafe - [discontinued code]. G - Good. PHOTO GUIDELINES: Inspection Photos: Please provide photos using guidelin Ally nem writch hyspector n Ally nem writch hy	ies below: eeis sriouid pe do einggr, Pr, P or scour, debris, wa	F2 - Fair. F1 - Fair. P3 - Poor. P1 - Poor. P - Poor. cumentea by pr aterway problem	C - Unsafe (Closed to U - Uninspectable. I - Inapplicable. notograpn	Public).	Problem De N - No Prob P - Possible K - Known I NA - Not Ap	e Problem. Problem.	Category Definitions: Maint Maintenance. Eng Engineering. Office - Bridge Office.	
INSPECTION PHOTOS								

Department of Transportation and Infrastructure, Government of Newfoundland and Labrador 2021.