12.7 m



GOVERNMENT OF
NEWFOUNDLAND
AND LABRADOR
Department of Transportation and Infrastructure

BRIDGE INSPECTION REPORT B07232021-9

Overall Length:

Date: 7/7/2021 Inspected By: McCaw J Category: Eng. - Engineering

BRIDGE INFORMATION

Site: 3-127 - SHOE COVE SOUTH BRIDGE

Route:

Year Built:1997Est: NoOverall Width:8.85 mYear Last Rehab.:Est: NoRoadway Width:6.7 m

Region: CENTRAL WEST Sidewalk Width: 1.45 m

Jurisdiction: Provincial Clearance to R.D. or N.W.L.:

Type of Structure: 03 - Reinforced Concrete Beam/Slab Max Depth of N.W.L.: 0 m

Purpose of Structure:04 - Over Non-Navigable WatersSpans:

01 - Aluminum Rail Type of Handrail: Span No.: Length Span No.: Length 01 - Concrete Roadway Surface: 1 8.5 4 02 - Adequate 2 0 5 0 Alignment Vertical: 3 0 6 0 02 - Adequate Alignment Horizontal:

Restrictions: No

BRIDGE PHOTOS





SUBSTRUCTURE

Condition: G - Good Bearings: I - Inapplicable

Bearing Seat: G - Good

Comments:

SUPERSTRUCTURE

Condition: G - Good Expansion Joints: I - Inapplicable

Comments:

DECK

Condition: F2 - Fair **Curbs:** F1 - Fair

Hand Rail: F2 - Fair **Roadway Condition:** F1 - Fair

Access to Daily	I Inapplicable			
Approach Rail:	I - Inapplicable			
Comments:	Rail has impact damage. Patching on surface at ends of structure. Wear to curbs and sidewalks.			
HYDROLOGY				
Water Velocity:	0.1 m/s	Ice Problem:	N - No Problem	
Water Depth:	0.3 m	Scour Problem:	N - No Problem	
Waterway:	01 - Adequate	Debris Problem:	N - No Problem	
Comments:				
REPLACEMENT/REHAB	ILITATION			
Next Rehab. Date:	2030	Replacement Year:	2075	
Antic. Rehab. Cost:	\$150000	Replacement Cost:	\$1500000	
Recommendations:	Repair plow damage. Fix the curb/sidewalk damage.			
OBSERVATIONS				
Overall Condition:	F2 - Fair	Requires Further Inspection:	No	
Additional Observations:	Parking ok. Hazards: traffic, slipping, wate	r		
LEGEND: Condition Definitions: 1 - *Good - [discontinued code]. 2 - *Fair - [discontinued code]. 3 - *Poor - [discontinued code]. 4 - *Unsafe - [discontinued code]. G - Good. PHOTO GUIDELINES: Inspection Photos: Please provide photos using guideling Any tem wnich inspector Any tem wnich inspector Any verdence of known ice	F2 - Fair. C - Unsafe (Closed to F1 - Fair. U - Uninspectable. P3 - Poor. I - Inapplicable. P1 - Poor. P - Poor. P - Poor. nes below: eeis should be documented by pnotograpn eing P3, P1, P1, or C, scour, debris, waterway problems	Public). N - N P - P K - K	lem Definitions: o Problem. ossible Problem. nown Problem. Not Applicable. Category Definitions: Maint Maintenance. Eng Engineering. Office - Bridge Office.	
INSPECTION PHOTOS				

Department of Transportation and Infrastructure, Government of Newfoundland and Labrador 2021.