

GOVERNMENT OF
NEWFOUNDLAND
AND LABRADOR
Department of Transportation and Infrastructure

BRIDGE INSPECTION REPORT B07162021-2

Date: 7/6/2021 Inspected By: McCaw J Category: Eng. - Engineering

BRIDGE INFORMATION

Site: 3-051 - WESTERN ARM BROOK BRIDGE

Route: 350

Year Built: 1983 Est: No Year Last Rehab.: Est: No

Region: CENTRAL WEST

Jurisdiction: Provincial

Type of Structure: 01 - AASH to Girder

Purpose of Structure: 04 - Over Non-Navigable Waters

Type of Handrail: 01 - Aluminum Rail

Roadway Surface: 01 - Concrete

Alignment Vertical: 01 - Good

Alignment Horizontal: 01 - Good

Restrictions: No

Overall Length:

38 **m**

Overall Width: Roadway Width: 9 **m** 8 **m**

Sidewalk Width:

0 **m**

Clearance to R.D. or

•

Max Depth of N.W.L.:

2 **m**

3.4 m

Spans:

N.W.L.:

Span No.:	<u>Length</u>	Span No.:	<u>Length</u>
1	20.2	4	0
2	0	5	0
3	0	6	0

BRIDGE PHOTOS





SUBSTRUCTURE

Condition: F2 - Fair **Bearings:** F2 - Fair

Bearing Seat: F2 - Fair

Comments:

SUPERSTRUCTURE

Condition: F2 - Fair Expansion Joints: U - Uninspectable

Comments: Joints not visible

DECK

Condition: P1 - Poor Curbs: F2 - Fair

Hand Rail: F2 - Fair **Roadway Condition:** F2 - Fair

Annyoosh Boile	F2 - Fair				
Approach Rail:	· - · · · ·				
Comments:	Many holes in deck surface. Rebar exposed in numerous spots.				
HYDROLOGY					
Water Velocity:	2.0 m/s	Ice Problem:	N - No Problem		
Water Depth:	1.5 m	Scour Problem:	N - No Problem		
Waterway:	01 - Adequate	Debris Problem:	N - No Problem		
Comments:					
REPLACEMENT/REHAB	ILITATION				
Next Rehab. Date:	2021	Replacement Year:	2045		
Antic. Rehab. Cost:	\$200000	Replacement Cost:	\$400000		
Recommendations:	Deck repair by overlay. New guiderail-structures				
OBSERVATIONS					
Overall Condition:	F2 - Fair	Requires Further Inspection:	No		
Additional Observations:	P- Deck surface, Remainder F2. Parking required partial blockage of one lane. Hazards: traffic, slipping, water				
LEGEND: Condition Definitions: 1 - *Good - [discontinued code]. 2 - *Fair - [discontinued code]. 3 - *Poor - [discontinued code]. 4 - *Unsafe - [discontinued code]. G - Good. PHOTO GUIDELINES: Inspection Photos: Please provide photos using guideline any item which inspector any item which inspector all items noted above as beautiful and items	F2 - Fair. C - Unsafe (Closed to F1 - Fair. U - Uninspectable. P3 - Poor. I - Inapplicable. P1 - Poor. P - Poor. P - Poor. Peets should be documented by photograph eing P3. P1. Pro or C, scourl, debris, waterway problems	Problem D Public). N - No Pro P - Possib K - Known NA - Not A	blem. Maint Maintenance. le Problem. Eng Engineering. Problem. Office - Bridge Office.		
INSPECTION PHOTOS					

Department of Transportation and Infrastructure, Government of Newfoundland and Labrador 2021.