

GOVERNMENT OF
NEWFOUNDLAND
AND LABRADOR
Department of Transportation and I

## BRIDGE INSPECTION REPORT B01142021-16

Department of Transportation and Infrastructure Date: 11/7/2020 Inspected By: Mike Fleming Category: Eng. - Engineering **BRIDGE INFORMATION** Site: 4-086 - BIG EAST RIVER BRIDGE (NO.2) 46.8 m Route: **Overall Length:** 1965 Year Built: Est: Yes **Overall Width:** 11 m Year Last Rehab.: 1999 Est: No Roadway Width: 10 m Region: WEST COAST/NORTHERN Sidewalk Width: 0 **m** Clearance to R.D. or Jurisdiction: Provincial 5.9 m N.W.L.: Type of Structure: 01 - AASH to Girder  $0 \, \mathbf{m}$ Max Depth of N.W.L.: Purpose of Structure: 03 - Over Navigable Waters Spans: 01 - Aluminum Rail Type of Handrail: Span No.: Length Span No.: Length 01 - Concrete Roadway Surface: 1 31.1 4 01 - Good 2 0 5 0 Alignment Vertical: 3 0 6 0 01 - Good Alignment Horizontal: No Restrictions: **BRIDGE PHOTOS SUBSTRUCTURE** Condition: G - Good Bearings: G - Good G - Good **Bearing Seat:** Comments: **SUPERSTRUCTURE** G - Good F2 - Fair Condition: **Expansion Joints:** Minor damage noted to one section on the North expansion joint and unable to fully assess expansion joint seals Comments: due to accumulation of winter sand. **DECK** Condition: G - Good Curbs: G - Good Hand Rail: G - Good **Roadway Condition:** G - Good Approach Rail: G - Good Some settlement, transverse cracking and asphalt patching on approaches adjacent to expansion joints. Minor Comments: damage noted to one section on North expansion joint. **HYDROLOGY** Water Velocity: 0 m/s N - No Problem Ice Problem: Water Depth: 0 m Scour Problem: N - No Problem 01 - Adequate **Debris Problem:** N - No Problem Waterway:

Comments:							
REPLACEMENT/REHABILITATION							
Next Rehab. Date:	2021			Replacement Yea	ar:	2021	
Antic. Rehab. Cost:	\$0			Replacement Cos	st:	\$0	
Recommendations:							
OBSERVATIONS							
Overall Condition:	G - Good			Requires Further Inspection:	,	No	
Additional Observations:	Inspection p	ictures are o	on file.				
LEGEND: Condition Definitions:  1 - *Good - [discontinued code]. 2 - *Fair - [discontinued code]. 3 - *Poor - [discontinued code]. 4 - *Unsafe - [discontinued code]. G - Good. PHOTO GUIDELINES: Inspection Photos: Please provide photos using guideling any term which inspector in Any term which inspector in Any evidence of known ice	nes below: eens gnouing pe ao eing P3, P1, P. or , scour, debris, w.	F2 - Fair. F1 - Fair. F3 - Poor. P1 - Poor. P - Poor. cumented by pn	C - Unsafe (Closed to U - Uninspectable. I - Inapplicable. otograpn s	Public).	Problem De N - No Prob P - Possible K - Known NA - Not Ap	olem. e Problem. Problem.	Category Definitions: Maint Maintenance. Eng Engineering. Office - Bridge Office.
INSPECTION PHOTOS							

Department of Transportation and Infrastructure, Government of Newfoundland and Labrador 2021.