

	GOVERNMENT OF NEWFOUNDLAND AND LABRADOR Department of Transportation and Infrastructure	BRIDGE INSPECTION REPORT B01052021-9	
Date: 4/23/2020	Inspected By: Terrance Coates	Category: Eng. - Engineering	
BRIDGE INFORMATION			
Site:	4-126 - BLANCHE BROOK		
Route:		Overall Length:	33.8 m
Year Built:	1989	Est: No	Overall Width: 8.7 m
Year Last Rehab.:		Est: Yes	Roadway Width: 7.7 m
Region:	WEST COAST/NORTHERN		Sidewalk Width: 0 m
Jurisdiction:	Provincial	Clearance to R.D. or N.W.L.:	3.2 m
Type of Structure:	01 - AASH to Girder	Max Depth of N.W.L.:	0.4 m
Purpose of Structure:	03 - Over Navigable Waters		Spans:
Type of Handrail:	01 - Aluminum Rail	<u>Span No.:</u>	<u>Length</u>
Roadway Surface:	02 - Asphalt	1	28.1
Alignment Vertical:	01 - Good	2	0
Alignment Horizontal:	01 - Good	3	0
Restrictions:	No	4	0
		5	0
		6	0
BRIDGE PHOTOS			
SUBSTRUCTURE			
Condition:	G - Good	Bearings:	G - Good
		Bearing Seat:	G - Good
Comments:			
SUPERSTRUCTURE			
Condition:	G - Good	Expansion Joints:	G - Good
Comments:	No end blocks.		
DECK			
Condition:	G - Good	Curbs:	G - Good
Hand Rail:	G - Good	Roadway Condition:	G - Good
Approach Rail:	I - Inapplicable		
Comments:	No approach rail. Paved deck. Aluminum rail is good.		
HYDROLOGY			
Water Velocity:	0 m/s	Ice Problem:	K - Known Problem
Water Depth:	0 m	Scour Problem:	P - Possible Problem
Waterway:	01 - Adequate	Debris Problem:	K - Known Problem
Comments:	Large pieces of previous structure that was demolished have been left in the waterway potentially acting as a		

