

GOVERNMENT OF **NEWFOUNDLAND** AND LABRADOR Department of Transportation and Infrastructure

BRIDGE INSPECTION REPORT B01192021-9

Date: 5/20/2020 Inspected By: Mike Fleming

BRIDGE INFORMATION

Site: TCH-102 - CORNER BROOK INDUSTRIAL UNDERPASS

Route: Year Built: 1981 Est: No

Year Last Rehab.: Est: No

Region: WEST COAST/NORTHERN

Jurisdiction: Provincial

Type of Structure: 05 - Pre-stressed Concrete Slab

01 - Highway Grade Separation Purpose of Structure:

01 - Aluminum Rail Type of Handrail: 02 - Asphalt Roadway Surface: 01 - Good Alignment Vertical: 01 - Good

No Restrictions:

Category: Eng. - Engineering

67.8 m **Overall Length:**

12.4 m **Overall Width:** 10.6 m Roadway Width:

Sidewalk Width: 0 **m**

Clearance to R.D. or

N.W.L.:

Max Depth of N.W.L.: $0 \, \mathbf{m}$

Spans:

Span No.: Length Span No.: **Length** 1 14.6 4 14.6 2 15.3 5 0 3 15.3 6 0

5.4 **m**

BRIDGE PHOTOS

Alignment Horizontal:





SUBSTRUCTURE

G - Good Condition: G - Good Bearings:

> F2 - Fair **Bearing Seat:**

Comments:

SUPERSTRUCTURE

F2 - Fair F2 - Fair Condition: **Expansion Joints:**

One leaking expansion joint Comments:

DECK

G - Good G - Good Condition: Curbs:

G - Good G - Good Hand Rail: **Roadway Condition:**

Approach Rail:	F2 - Fair		
1			
Comments:	One section of approach rail damaged.		
HYDROLOGY			
Water Velocity:	0 m/s	Ice Problem:	NA - Not Applicable
Water Depth:	0 m	Scour Problem:	NA - Not Applicable
Waterway:	03 - Not Applicable	Debris Problem:	NA - Not Applicable
Comments:			
REPLACEMENT/REHABILITATION			
Next Rehab. Date:	2021	Replacement Year:	2021
Antic. Rehab. Cost:	\$0	Replacement Cost:	\$0
Recommendations:			
OBSERVATIONS			
Overall Condition:	G - Good	Requires Further Inspection:	No
Additional Observations:	Inspection pictures on file.		
LEGEND: Condition Definitions: 1 - 'Good - (discontinued code). 2 - 'Fair - (discontinued code). 3 - 'Poor - [discontinued code]. 4 - 'Unsafe - [discontinued code]. G - Good. PHOTO GUIDELINES: Inspection Photos: Please provide photos using guideling a provide photos using guideling and the provide photos using guideling and the photos using guideling and guideling and guideling and guideling and gui	F2 - Fair. C - Unsafe (Closed F1 - Fair. U - Uninspectable. P3 - Poor. I - Inapplicable. P1 - Poor. P - Poor. P - Poor. below: else should be documented by photograph in P3 P1 P or C scour, debris, waterway problems	to Public). N - No Pro	le Problem. Eng Engineering. Problem. Office - Bridge Office.
INSPECTION PHOTOS			

Department of Transportation and Infrastructure, Government of Newfoundland and Labrador 2021.