Newfoundland Labrador	GOVERNMENT OF NEWFOUNDLAI AND LABRADO Department of Transporta	NEWFOLINDI AND		BRIDGE INSPECTION REPORT B01182021-4					
Date: 5/27/2020	Inspected By: Mike		Category: Eng Engineering						
BRIDGE INFORMATIO	N								
Site:	4-063 - GILLAMS BRO	OOK BRIDGE							
Route:	440		C	Overall Leng	gth:	35.6 m			
Year Built:	1971	Est: No	C	Overall Width: Roadway Width:		10.8 m 9.2 m			
Year Last Rehab.:		Est: No	F						
Region:	WEST COAST/NORT	HERN	S	Sidewalk Width:		0 m			
Jurisdiction:	Provincial	Provincial		Clearance to R.D. or N.W.L.:		2.4 m			
Type of Structure:	01 - AASH to Girder		Ν	Max Depth o	of N.W.L.:	0.5 m			
Purpose of Structure:	03 - Over Navigable V	Vaters	S	Spans:					
Type of Handrail:	02 - Concrete Rail		5	Span No.:	<u>Length</u>	Span No.:	Length		
Roadway Surface:	02 - Asphalt			1	28.9	4	0		
Alignment Vertical:	02 - Adequate		:	2	0	5	0		
	01 - Good			3	0	6	0		
Alignment Horizontal:	01 - 0000		•	5	•				
Alignment Horizontal: Restrictions: BRIDGE PHOTOS	No								
Restrictions: BRIDGE PHOTOS			2004 6 28						
Restrictions: BRIDGE PHOTOS			vertical design of the second se	G - G					
Restrictions:	No		2004 6 28		bood				
Restrictions: BRIDGE PHOTOS	No		2004 6.29 Bearings: Bearing Seat:	- 	bood				
Restrictions: BRIDGE PHOTOS	No		2004 6.29 Bearings: Bearing Seat:	- 	bood				
Restrictions: BRIDGE PHOTOS SUBSTRUCTURE Condition: Comments:	No	rescence deposits not	2004 6.29 Bearings: Bearing Seat:	- 	iood				
Restrictions: BRIDGE PHOTOS SUBSTRUCTURE Condition: Comments: SUPERSTRUCTURE Condition:	No	rescence deposits not	Bearing Seat: ed on abutments.	G - G G - G	iood				
Restrictions: BRIDGE PHOTOS SUBSTRUCTURE Condition: Comments: SUPERSTRUCTURE	No	rescence deposits not	Bearing Seat: ed on abutments.	G - G G - G	iood				
Restrictions: BRIDGE PHOTOS SUBSTRUCTURE Condition: Comments: SUPERSTRUCTURE Condition: Condition:	No	rescence deposits not	Bearing Seat: ed on abutments.	G - G G - G	iood iood iood				

Approach Rail:	G - Good								
Comments:									
HYDROLOGY									
Water Velocity:	0 m/s		Ice Problem:		K - Known Prob	lem			
Water Depth:	0 m		Scour Problem:	ur Problem:		K - Known Problem			
Waterway:	01 - Adequate		Debris Problem:		K - Known Problem				
Comments:									
REPLACEMENT/REHAB	ILITATION								
Next Rehab. Date:	2021		Replacement Yea	ır:	2021				
Antic. Rehab. Cost:	\$0		Replacement Cos	st:	\$0				
Recommendations:									
OBSERVATIONS									
Overall Condition:	G - Good		Requires Further Inspection:		No				
Additional Observations:	No hazard markers. Picture	s on file.							
LEGEND: Condition Definitions: 1 - *Good - [discontinued code]. 2 - *Fair - [discontinued code]. 3 - *Poor - [discontinued code]. 4 - *Unsafe - [discontinued code]. G - Good. PHOTO GUIDELINES: Inspection Photos. Please provide photos using guidelir Please provide photos using guidelir All tems noted above as b Any evidence of known ice	F1 - Fair. U	- Unsafe (Closed to F - Uninspectable. Inapplicable.	² ublic).	Problem De N - No Prob P - Possible K - Known F NA - Not Ap	lem. Problem. Problem.	<u>Category Definitions:</u> Maint Maintenance. Erg Engineering. Office - Bridge Office.			
	Department of Transportation				0004				

Department of Transportation and Infrastructure, Government of Newfoundland and Labrador 2021.