

GOVERNMENT OF NEWFOUNDLAND AND LABRADOR

BRIDGE INSPECTION REPORT B01062021-2

Department of Transportation and Infrastructure Date: 5/19/2020 Inspected By: Mike Fleming Category: Eng. - Engineering **BRIDGE INFORMATION** Site: TCH-091 - GRAND BAY BRIDGE 59.6 m Route: **Overall Length:** 1988 **Overall Width:** Year Built: Est: No 15.2 m Year Last Rehab.: Est: No Roadway Width: 14.2 m Region: WEST COAST/NORTHERN Sidewalk Width: 0.5 **m** Clearance to R.D. or Jurisdiction: Provincial 1.5 m N.W.L.: Type of Structure: 01 - AASH to Girder Max Depth of N.W.L.: $0 \, \mathbf{m}$ Purpose of Structure: 03 - Over Navigable Waters Spans: 01 - Aluminum Rail Type of Handrail: Span No.: Length Span No.: Length 02 - Asphalt Roadway Surface: 1 40.9 4 01 - Good 2 0 5 0 Alignment Vertical: 3 0 6 0 01 - Good Alignment Horizontal: No Restrictions: **BRIDGE PHOTOS SUBSTRUCTURE** Condition: G - Good Bearings: G - Good G - Good **Bearing Seat:** Note: could not fully assess bearings and bearing seats due to high water levels. Some efflorescence deposits Comments: noted on the abutments. **SUPERSTRUCTURE** G - Good P3 - Poor Condition: **Expansion Joints:** Comments: Expansion joints damaged and leaking **DECK** Condition: G - Good Curbs: G - Good Hand Rail: G - Good **Roadway Condition:** G - Good Approach Rail: F2 - Fair Some minor damage noted on end-blocks and winter sand accumulation near approach rail. Asphalt patching Comments: noted on both approaches **HYDROLOGY** N - No Problem Water Velocity: 0 m/s Ice Problem: Water Depth: 0 m Scour Problem: N - No Problem Waterway: 01 - Adequate **Debris Problem:** N - No Problem

Comments:						
REPLACEMENT/REHAB	ILITATION					
Next Rehab. Date:	2021		Replacement Yea	r:	2021	
Antic. Rehab. Cost:	\$0		Replacement Cos	it:	\$0	
Recommendations:	Recommend to replace exp	pansion joints				
OBSERVATIONS						
Overall Condition:	G - Good		Requires Further Inspection:		No	
Additional Observations:	no hazard markers in place. Inspection pictures are on file due to upload size restrictions.					
LEGEND: Condition Definitions: 1 - *Good - [discontinued code]. 2 - *Fair - [discontinued code]. 3 - *Poor - [discontinued code]. 4 - *Unsafe - [discontinued code]. G - Good. PHOTO GUIDELINES: Inspection Photos: Please provide photos using guideling any urem which inspector of All tems noted above as All tems noted above as Any evidence of known ice	F1 - Fair. U P3 - Poor. P1 - Poor. P - Poor.	C - Unsafe (Closed to U - Uninspectable. I - Inapplicable.	•	Problem Det N - No Probl P - Possible K - Known P NA - Not Ap	em. Problem. Problem.	Category Definitions: Maint Maintenance. Eng Engineering. Office - Bridge Office.
INSPECTION PHOTOS						

Department of Transportation and Infrastructure, Government of Newfoundland and Labrador 2021.