15.25 m

6.1 **m**

4.47 m

0 **m**

2.2 m

1 m

Length

Length Span No.:



GOVERNMENT OF
NEWFOUNDLAND
AND LABRADOR
Department of Transportation and Infrastructure

BRIDGE INSPECTION REPORT B01132021-2

Overall Length:

Overall Width:

Roadway Width:

Sidewalk Width:

N.W.L.:

Spans:

Span No.:

Clearance to R.D. or

Max Depth of N.W.L.:

Date: 11/6/2020 Inspected By: Mike Fleming Category: Eng. - Engineering

BRIDGE INFORMATION

Site: 4-170 - Green Island Brook Community Bridge

Route: 430-62

Year Built: 2006 Est: No
Year Last Rehab.: Est: No

Region: WEST COAST/NORTHERN

Jurisdiction: Provincial

Type of Structure: 09 - Bailey Bridge

Purpose of Structure: 03 - Over Navigable Waters

Type of Handrail: 04 - Steel Rail

03 - Timber Roadway Surface: 1 15.25 4 01 - Good 2 0 5 0 Alignment Vertical: 3 0 6 0 01 - Good Alignment Horizontal:

Restrictions: No

BRIDGE PHOTOS

SUBSTRUCTURE

Condition: G - Good **Bearings:** G - Good

Bearing Seat: G - Good

Comments:

SUPERSTRUCTURE

Condition: G - Good Expansion Joints: I - Inapplicable

Comments:

DECK

Condition: F2 - Fair **Curbs**: F2 - Fair

Hand Rail: G - Good **Roadway Condition:** F2 - Fair

Approach Rail: F2 - Fair

Comments: Approach rail damaged at two buried ends. Longitudinal deck boards are moderately worn and damaged;

damaged fasteners noted. Minor damage also noted on curb.

HYDROLOGY

Water Velocity: 0 m/s Ice Problem: N - No Problem

Water Depth: 0 m Scour Problem: N - No Problem

Waterway: 01 - Adequate Debris Problem: N - No Problem

Comments:					
REPLACEMENT/REHAB	ILITATION				
Next Rehab. Date:	2021		Replacement Yea	r: 2021	
Antic. Rehab. Cost:	\$0		Replacement Cos	t : \$0	
Recommendations:					
OBSERVATIONS					
Overall Condition:	G - Good		Requires Further Inspection:	No	
Additional Observations:	One section of chain lin file.	k fence missing on	the upstream side.	No hazard markers i	n place. Note: Pictures are on
LEGEND: Condition Definitions: 1 - "Good - [discontinued code]. 2 - "Fair - [discontinued code]. 3 - "Poor - [discontinued code]. 6 - Good. PHOTO GUIDELINES: Inspection Photos: Please provide photos using guideling and the provide photos using guideling and guideling and guideling and guideling and guideling and guideling and g	F2 - Fair. F1 - Fair. P3 - Poor. P1 - Poor. P - Poor. P - Poor. ees spould be documented by preing P3 or cour, debris, waterway problem	C - Unsafe (Closed to U - Uninspectable. I - Inapplicable. notograpn	Public).	Problem Definitions: N - No Problem. P - Possible Problem. K - Known Problem. NA - Not Applicable.	Category Definitions: Maint Maintenance. Eng Engineering. Office - Bridge Office.
INSPECTION PHOTOS	, scour, debris, waterway problem	15			

Department of Transportation and Infrastructure, Government of Newfoundland and Labrador 2021.