Newfoundland Labrador	GOVERNMENT OF NEWFOUNDLAND AND LABRADOR Department of Transportation and Infrastructure		BRIDGE INSPECTION REPORT B01182021-24 Category: Eng Engineering					
Date: 5/5/2020	Inspected By: Mike Flem							
BRIDGE INFORMATION	l							
Site:	TCH-133 - MOLLICHIGNIC	K BIRDGE						
Route:				Overall Leng	gth:	17.5 <b>m</b>		
Year Built:	1964	Est: No		Overall Widt	th:	9.8 <b>m</b>		
Year Last Rehab.:	2001	Est: No		Roadway Width:			8.3 <b>m</b>	
Region:	WEST COAST/NORTHERI	/EST COAST/NORTHERN Sidewalk Width: 0 r				0 <b>m</b>		
Jurisdiction:	Provincial			Clearance to R.D. or N.W.L.: 3.6 m				
Type of Structure:	04 - Rigid Frame			Max Depth of N.W.L.: 0 m				
Purpose of Structure:	03 - Over Navigable Waters	5		Spans:				
Type of Handrail:	01 - Aluminum Rail			<u>Span No.:</u>	Length	Span No.:	Length	
Roadway Surface:	02 - Asphalt			1	15.2	4	0	
Alignment Vertical:	01 - Good			2	0	5	0	
Alignment Horizontal:	01 - Good			3	0	6	0	
Restrictions:	No							
BRIDGE PHOTOS								
SUBSTRUCTURE								
Condition:	F2 - Fair		Bearings:	I - Inapplicable				
			Bearing Seat:	I - Inapplicable				
Comments:								
SUPERSTRUCTURE								
Condition:	F2 - Fair		Expansion Joints:	Expansion Joints: I - Inapplicable				
Comments:	Cracking and spalling on e	slab.						
DECK								
Condition:	F2 - Fair		Curbs:	F2 - F	Fair			
Hand Rail:	P3 - Poor Roadway		Roadway Condition	n: F2 - Fair				
Approach Rail:	P3 - Poor							
Comments:	Hand rail damaged on both	n sides. Spallin	ig on deck soffit.					
HYDROLOGY								
Water Velocity:	0 <b>m/s</b>		Ice Problem: N - No Pr		o Problem			
Water Depth:	0 <b>m</b>		Scour Problem:	Problem: N - No Problem				
Waterway:	01 - Adequate		Debris Problem:	N - N	o Problem			
Comments:								

REPLACEMENT/REHABILITATION								
Next Rehab. Date:	2021		Replacement Yea	<b>r:</b> 2021				
Antic. Rehab. Cost:	\$0		Replacement Cos	st: \$0				
Recommendations:								
OBSERVATIONS								
Overall Condition:	F2 - Fair		Requires Further Inspection:	No				
Additional Observations: Winter sand accumulation along curb. Inspection pictures on file.								
LEGEND: Condition Definitions: 1 - *Good - [discontinued code]. 2 - *Fair - [discontinued code]. 3 - *Poor - [discontinued code]. 4 - *Unsafe - [discontinued code]. G - Good. PHOTO GUIDELINES: Inspection Photos: Please provide photos using guidelir Please provide photos using guidelir Mainter monted above as ba Any evidence of known ice	F2 - Fair. F1 - Fair. P3 - Poor. P1 - Poor. P - Poor. P - Poor. scour; debris, waterway problem	C - Unsafe (Closed to U - Uninspectable. I - Inapplicable. lotograpn	Public).	Problem Definitions: N - No Problem. P - Possible Problem. K - Known Problem. NA - Not Applicable.	<u>Category Definitions:</u> Maint - Maintenance. Eng Engineering. Office - Bridge Office.			

Department of Transportation and Infrastructure, Government of Newfoundland and Labrador 2021.