Newfoundland Labrador	GOVERNMENT OF NEWFOUNDLAND AND LABRADOR Department of Transportation	BRIDGE INSPECTION REPORT B01202021-6 Category: Eng Engineering						
Date: 5/27/2020	Inspected By: Mike Fle							
BRIDGE INFORMATION	l							
Site:	TCH-158 - PASADENA W	EST ACCESS	(EASTBOUND)					
Route:				Overall Len	gth:	26.7 <b>m</b>		
Year Built:	1999	Est: No		Overall Wid	th:	13.5 <b>m</b>		
Year Last Rehab.:	Est: No			Roadway Width:		12.8 <b>m</b>		
Region:	WEST COAST/NORTHERN			Sidewalk Width:		0 <b>m</b>		
Jurisdiction:	Provincial			Clearance to R.D. or N.W.L.:		5 <b>m</b>		
Type of Structure:	04 - Rigid Frame			Max Depth of N.W.L.:		0 <b>m</b>		
Purpose of Structure:	01 - Highway Grade Separation			Spans:				
Type of Handrail:	05 - Concrete Barrier			Span No.:	Length	Span No.:	Length	
Roadway Surface:	01 - Concrete			1	16.5	4	0	
Alignment Vertical:	01 - Good			2	0	5	0	
Alignment Horizontal:	01 - Good			3	0	6	0	
Restrictions:	No							
BRIDGE PHOTOS								
SUBSTRUCTURE								
Condition:	G - Good		Bearings:	G - C	Good			
			Bearing Seat:	G - (	Good			
Comments:								
SUPERSTRUCTURE								
Condition:	F2 - Fair Expansion Join			s: U - Uninspectable				
Comments:	Minor hairline cracks with efflorescence deposits noted on underside of deck.							
DECK								
Condition:	G - Good		Curbs:	G - 0	Good			
Hand Rail:	G - Good		Roadway Conditio	<b>n:</b> G-C	Good			
Approach Rail:	G - Good							
Comments:	minor damage to approac	ch rail noted.						
HYDROLOGY								
Water Velocity:	0 <b>m/s</b>		Ice Problem:	NA -	Not Applica	able		
Water Depth:	0 <b>m</b>		Scour Problem:	NA -	Not Applica	able		
Waterway:	03 - Not Applicable		Debris Problem:	NA -	Not Applica	able		
Comments:								

REPLACEMENT/REHABILITATION										
Next Rehab. Date:	2021			Replacement Yea	ar:	2021				
Antic. Rehab. Cost:	\$0			Replacement Co	st:	\$0				
Recommendations:										
OBSERVATIONS										
Overall Condition:	G - Good			Requires Further Inspection:		No				
Additional Observations:	Inspection pic	tures on file								
LEGEND: Condition Definitions: 1 - *Good - [discontinued code]. 2 - *Fair - [discontinued code]. 3 - *Poor - [discontinued code]. 4 - *Unsafe - [discontinued code]. G - Good. PHOTO GUIDELINES: Inspection Photos: Please provide photos using guideling Please provide photos using guideling Any videm winch inspector n Any videm code above as bo Any evidence of known icce	F P P	2 - Fair. 1 - Fair. 3 - Poor. 1 - Poor. - Poor. mentea by pnot rway problems	C - Unsafe (Closed to U - Uninspectable. I - Inapplicable. ograpn	Public).	Problem Do N - No Prot P - Possibi K - Known NA - Not Aj	e Problem. Problem. Problem.	Category Definitions: Maint Maintenance. Eng Engineering. Office - Bridge Office.			
INSPECTION PHOTOS	, , <b></b>									

Department of Transportation and Infrastructure, Government of Newfoundland and Labrador 2021.