

GOVERNMENT OF
NEWFOUNDLAND
AND LABRADOR
Department of Transportation and Infrastructure

BRIDGE INSPECTION REPORT B01142021-7

Date: 11/6/2020 Inspected By: Mike Fleming Category: Eng. - Engineering **BRIDGE INFORMATION** Site: 4-083 - RUSHY BROOK BRIDGE (RODDICKTON) 20.6 m Route: **Overall Length:** 1967 Year Built: Est: No **Overall Width:** 8.9 m Year Last Rehab.: Est: No Roadway Width: $7.4 \, m$ Region: WEST COAST/NORTHERN Sidewalk Width: 0 **m** Clearance to R.D. or Jurisdiction: Provincial 3.1 m N.W.L.: Type of Structure: 01 - AASH to Girder 0.2 m Max Depth of N.W.L.: Purpose of Structure: 03 - Over Navigable Waters Spans: 02 - Concrete Rail Type of Handrail: Span No.: Length Span No.: Length 02 - Asphalt Roadway Surface: 1 14.6 4 01 - Good 2 0 5 0 Alignment Vertical: 3 0 6 0 02 - Adequate Alignment Horizontal: No Restrictions: **BRIDGE PHOTOS SUBSTRUCTURE** Condition: F2 - Fair Bearings: G - Good G - Good **Bearing Seat:** Comments: Moderate delamination noted on abutment headwalls **SUPERSTRUCTURE** G - Good P3 - Poor Condition: **Expansion Joints:** Comments: Rubber seals in expansion joints leaking on abutment headwalls and bearing seats. **DECK** G - Good G - Good Condition: Curbs: Hand Rail: G - Good G - Good **Roadway Condition:** G - Good Approach Rail: Asphalt patching noted on both sides of expansion joints and on deck concentrated towards centerline. Minor Comments: damage noted on top of one end-block. **HYDROLOGY** Water Velocity: 0 m/s Ice Problem: N - No Problem $0 \, \mathbf{m}$ Scour Problem: N - No Problem Water Depth: 01 - Adequate **Debris Problem:** N - No Problem Waterway:

Comments:					
REPLACEMENT/REHAB	ILITATION				
Next Rehab. Date:	2021		Replacement Yea	r: 2021	
Antic. Rehab. Cost:	\$0		Replacement Cos	t : \$0	
Recommendations:					
OBSERVATIONS					
Overall Condition:	G - Good		Requires Further Inspection:	No	
Additional Observations:	Inspection pictures on fi	le			
LEGEND: Condition Definitions: 1 - *Good - [discontinued code]. 2 - *Fair - [discontinued code]. 3 - *Poor - [discontinued code]. 4 - *Unsafe - [discontinued code]. G - Good. PHOTO GUIDELINES: Inspection Photos: Please provide photos using guideling Any utem which inspector in Any utem which inspector in Any vidence of known ice	F2 - Fair. F1 - Fair. F3 - Poor. P1 - Poor. P - Poor. P - Poor. nes below: ees snouin ee documented by preing P3 P1, p or C, sour, debris, waterway problem.	C - Unsafe (Closed to U - Uninspectable. I - Inapplicable. notograpn	Public).	Problem Definitions: N - No Problem. P - Possible Problem. K - Known Problem. NA - Not Applicable.	Category Definitions: Maint Maintenance. Eng Engineering. Office - Bridge Office.
Any evidence of known ice INSPECTION PHOTOS	, scour, debris, waterway problem	ıs			

Department of Transportation and Infrastructure, Government of Newfoundland and Labrador 2021.