Newfoundland Labrador	GOVERNMENT OF NEWFOUNDLAND AND LABRADOR Department of Transportation and Infrastructure		BRIDGE INSPECTION REPORT B01142021-13					
Date: 11/6/2020	Inspected By: Mike Flem		Cate	gory: Eng.	- Engineering			
BRIDGE INFORMATION								
Site:	4-208 - WEST BROOK BRI	DGE						
Route:				Overall Leng	gth:	33.2 m		
Year Built:	1998	Est: No		Overall Widt	:h:	10.1 m		
Year Last Rehab.:		Est: No		Roadway W	idth:	8.6 m		
Region:	WEST COAST/NORTHERN			Sidewalk Width:		0 m		
Jurisdiction:	Provincial			Clearance to R.D. or N.W.L.:		4.9 m		
Type of Structure:	01 - AASH to Girder			Max Depth of N.W.L.:		0 m		
Purpose of Structure:	03 - Over Navigable Waters	6		Spans:	špans:			
Type of Handrail:	01 - Aluminum Rail			Span No.:	<u>Length</u>	Span No.:	Length	
Roadway Surface:	02 - Asphalt			1	19.7	4	0	
Alignment Vertical:	01 - Good			2	0	5	0	
Alignment Horizontal:	01 - Good			3	0	6	0	
Restrictions:	No							
BRIDGE PHOTOS								
SUBSTRUCTURE								
Condition:	G - Good		Bearings:	G - Good				
			Bearing Seat:	G - G	iood			
Comments:								
SUPERSTRUCTURE								
Condition:	G - Good		Expansion Joints:	Expansion Joints: P3 - Poor				
Comments:	Expansion joint damage noted on the center of one expansion joint; both expansion joints leaking water on the abutments and bearing seats. Light corrosion noted on steel girders.							
DECK								
Condition:	G - Good		Curbs:	G - G	iood			
Hand Rail:	G - Good		Roadway Condition	n: G-G	iood			
Approach Rail:	G - Good							
Comments:								
HYDROLOGY								
Water Velocity:	0 m/s		Ice Problem:	N - N	o Problem			
Water Depth:	0 m		Scour Problem:	N - N	o Problem			
Waterway:	01 - Adequate		Debris Problem:	NI NI	o Problem			

Comments:									
REPLACEMENT/REHAB	ILITATION								
Next Rehab. Date:	2021		Replacement Yea	ır:	2021				
Antic. Rehab. Cost:	\$0		Replacement Cos	st:	\$0				
Recommendations:	Expansion joints should be repaired to prevent leakage.								
OBSERVATIONS									
Overall Condition:	G - Good		Requires Further Inspection:		No				
Additional Observations:	Inspection pictures on fi	le.							
LEGEND: Condition Definitions: 1 - *Good - [discontinued code]. 2 - *Fair - [discontinued code]. 3 - *Poor - [discontinued code]. 4 - *Unsafe - [discontinued code]. G - Good. PHOTO GUIDELINES: Inspection Photos Please provide photos using guidelir Please provide photos using guidelir All terms more above as b Any evidence of known ice	F2 - Fair. F1 - Fair. P3 - Poor. P1 - Poor. P - Poor. P - Poor. eens snoune e occumentee by pn eing P3 P1 P, or C	C - Unsafe (Closed to U - Uninspectable. I - Inapplicable. otograpn s	Public).	Problem De N - No Prob P - Possible K - Known i NA - Not Ap	e Problem. Problem.	Category Definitions: Maint Maintenance. Eng Engineering. Office - Bridge Office.			
INSPECTION PHOTOS									

Department of Transportation and Infrastructure, Government of Newfoundland and Labrador 2021.