

Churchill River, Additional Ice Thickness Measurements - Dec 3, 2019

| Site | Longitude | Latitude | Ice Thickness (m) |
|-------------------|------------|-----------|----------------------|
| Between N5 and N6 | -60.612499 | 53.258072 | 0.000 |
| Between N6 and N7 | -60.320271 | 53.283237 | 0.000 |
| Mud Lake A | -60.170254 | 53.322330 | 0.000 |
| Mud Lake B | -60.176342 | 53.325226 | - |
| Mud Lake C | -60.186268 | 53.329140 | 0.070 |

NOTE:

Ice thickness is not consistent it varies from place to place and changes with time. Variations in thickness and strength may be caused by a variety of factors including air temperature, snow cover, water depth, and water currents. Data users are advised to take note of this.