
MINERAL DEVELOPMENT DIVISION -REHABILITATION PROJECTS

WHALESBACK MINE ABANDONED MILL SITE, SPRINGDALE





Using a hydraulic hammer to break up the concrete foundations.



Using a hydraulic hammer to break up the concrete foundations.



Cutting off the reinforcing bars.

Stockpiled acid generating material.




Cutting off the reinforcing bars.




The reinforcing bars were bent down for safety reasons.



All acid generating material had to be gathered and stockpiled.






Collapse.




A view of the worksite from above. (before)



A view of the worksite after completion.





A view of the worksite after completion.



COLLIER POINT ABANDONED BARITE MINE, NORMAN'S COVE




View of abandoned Barite Mine at Collier Point, May 2005.

After Rehabilitation.



View of Safety Berm at the base of the slope.



View of Safety Berm at the base of the slope.