

	GOVERNMENT OF NEWFOUNDLAND AND LABRADOR Department of Transportation and Infrastructure	BRIDGE INSPECTION REPORT B02072024-15
Date: 12/11/2023	Inspected By: Sharron/Rebello	Category: Eng. - Engineering
BRIDGE INFORMATION		
Site:	TCH-095 - UNION STREET UNDERPASS - R	
SUBSTRUCTURE		
Condition:	F2 - Fair	Bearings: F2 - Fair
		Bearing Seat: F2 - Fair
Comments:	Minor cracks in both abutments, hairline cracking in piers	
SUPERSTRUCTURE		
Condition:	F2 - Fair	Expansion Joints: F2 - Fair
Comments:	Backer rod missing behind sealant on west sidewalk joint	
DECK		
Condition:	F2 - Fair	Curbs: F2 - Fair
Hand Rail:	F2 - Fair	Roadway Condition: F2 - Fair
Approach Rail:	F2 - Fair	
Comments:	Small spall on sidewalks on southwest expansion areas, hairline cracks in curb overhangs	
HYDROLOGY		
Water Velocity:	0 m/s	Ice Problem: NA - Not Applicable
Water Depth:	0 m	Scour Problem: NA - Not Applicable
Waterway:	01 - Adequate	Debris Problem: NA - Not Applicable
Comments:		
REPLACEMENT/REHABILITATION		
Next Rehab. Date:		Replacement Year:
Antic. Rehab. Cost:	\$0	Replacement Cost:
Recommendations:		
OBSERVATIONS		
Overall Condition:	F2 - Fair	Requires Further Inspection: No
Additional Observations:	Rehab in 2020	

Department of Transportation and Infrastructure, Government of Newfoundland and Labrador 2024.