

		GOVERNMENT OF NEWFOUNDLAND AND LABRADOR Department of Transportation and Infrastructure		BRIDGE INSPECTION REPORT B07292025-15	
Date: 7/29/2025		Inspected By: M.Snooks		Category: Eng. - Engineering	
BRIDGE INFORMATION					
Site:		TCH-125 - RIVERSIDE DRIVE UNDERPASS - R			
SUBSTRUCTURE					
Condition:	F2 - Fair	Bearings:	F1 - Fair		
		Bearing Seat:	F1 - Fair		
Comments:	Leaking on top of bearing seat. Moderate corrosion on bearings.				
SUPERSTRUCTURE					
Condition:	F1 - Fair	Expansion Joints:	F1 - Fair		
Comments:	Expansion seal full of debris and missing in sections. Some areas of asphalt patching over expansion joints. Light spalling noted on the underside of deck.				
DECK					
Condition:	F1 - Fair	Curbs:	F1 - Fair		
Hand Rail:	F1 - Fair	Roadway Condition:	F1 - Fair		
Approach Rail:	F1 - Fair				
Comments:	Significant asphalt delamination on deck and approach slabs. Damage on handrail and Approach Rail.				
HYDROLOGY					
Water Velocity:	0 m/s	Ice Problem:	NA - Not Applicable		
Water Depth:	0 m	Scour Problem:	NA - Not Applicable		
Waterway:	03 - Not Applicable	Debris Problem:	NA - Not Applicable		
Comments:					
REPLACEMENT/REHABILITATION					
Next Rehab. Date:		Replacement Year:			
Antic. Rehab. Cost:	\$0	Replacement Cost:	\$0		
Recommendations:					
OBSERVATIONS					
Overall Condition:	F1 - Fair	Requires Further Inspection:	No		
Additional Observations:					

Department of Transportation and Infrastructure, Government of Newfoundland and Labrador 2026.