Temple's Backhoe Services Ltd.

121 Main Street Bishop's Falls, NL. A0H1C0

Environmental Assessment

Name of Cooperate Body: Temple's Backhoe Services

Address:121 Main Street

Chief Executive Officer:

Name: Robert Temple Official Title: owner

Address: 121 Main Street, Bishop's Falls Telephone #: 258-7256, cell#: 486-7256

Principal contact person for the purpose of Environmental Assessment:

Name: Robert Temple
Official Title: Owner

Address: 121 Main Street

Telephone #: 258-7256, cell # 486- 7256

The Undertaking:

Nature of the undertaking: Gravel Pit

Purpose/ Rationale/ Need for undertaking: Pitrun, sand and gravel

Description of the Undertaking:

Geographical Location: Botwood Highway

Physical features: Existing quarry pit already striped. There are no buildings to be

erected and there is already an existing road to the quarry.

Construction: No construction to take place because the quarry is already existing.

Operation: Removal of sand and gravel and pitrun- May to October.

Tel: (709) 258-7256,486-7256 * Email: templesbackhoe@hotmail.com

Occupations: There will be two (2) employees. The duration on employment will last as long as the quarry source is in demand.

Approval of the undertaking: Mines and Energy.

Schedule: As soon as approval is given up to the first snowfall of the year.

Funding: This project will be self funded by Temple's Backhoe Services Ltd- Mr Robert Temple.

Date

Signature of chief Executive Officer

<u>Tel:(709)</u> 258-7256 , 486-7256 * Email: templesbackhoe@hotmail.com

Prian Borling / Como Brtwood flux Pormad Life All count permits (20°50)