

	GOVERNMENT OF NEWFOUNDLAND AND LABRADOR Department of Transportation and Infrastructure	<b>BRIDGE INSPECTION REPORT</b> <b>B05242024-6</b>
<b>Date:</b> 5/24/2024	<b>Inspected By:</b> L Christensen	<b>Category:</b> Office - Bridge Office
<b>BRIDGE INFORMATION</b>		
<b>Site:</b>	1-081 - POINT VERDE BROOK BRIDGE - R100	
<b>SUBSTRUCTURE</b>		
<b>Condition:</b>	F1 - Fair	<b>Bearings:</b> P3 - Poor
		<b>Bearing Seat:</b> F1 - Fair
<b>Comments:</b>	Rehab repairs look good	
<b>SUPERSTRUCTURE</b>		
<b>Condition:</b>	F1 - Fair	<b>Expansion Joints:</b> F1 - Fair
<b>Comments:</b>	Expansion joint need to be cleaned One large girder repair has cracked off, attached to abutment which likely caused failure	
<b>DECK</b>		
<b>Condition:</b>	F2 - Fair	<b>Curbs:</b> G - Good
<b>Hand Rail:</b>	G - Good	<b>Roadway Condition:</b> F2 - Fair
<b>Approach Rail:</b>	G - Good	
<b>Comments:</b>		
<b>HYDROLOGY</b>		
<b>Water Velocity:</b>	0 m/s	<b>Ice Problem:</b> NA - Not Applicable
<b>Water Depth:</b>	0 m	<b>Scour Problem:</b> N - No Problem
<b>Waterway:</b>	01 - Adequate	<b>Debris Problem:</b> N - No Problem
<b>Comments:</b>		
<b>REPLACEMENT/REHABILITATION</b>		
<b>Next Rehab. Date:</b>		<b>Replacement Year:</b>
<b>Antic. Rehab. Cost:</b>	\$0	<b>Replacement Cost:</b> \$0
<b>Recommendations:</b>		
<b>OBSERVATIONS</b>		
<b>Overall Condition:</b>	F1 - Fair	<b>Requires Further Inspection:</b> No
<b>Additional Observations:</b>	Happy with quality of rehab	

Department of Transportation and Infrastructure, Government of Newfoundland and Labrador 2024.