

		GOVERNMENT OF NEWFOUNDLAND AND LABRADOR Department of Transportation and Infrastructure		BRIDGE INSPECTION REPORT B11132024-14	
Date: 11/13/2024		Inspected By: Lars/Sarah		Category: Office - Bridge Office	
BRIDGE INFORMATION					
Site:		1-012 - ADMIRAL'S COVE BRIDGE - R			
SUBSTRUCTURE					
Condition:	F2 - Fair	Bearings:	I - Inapplicable		
		Bearing Seat:	I - Inapplicable		
Comments:	Minor map cracking on wing walls.				
SUPERSTRUCTURE					
Condition:	F1 - Fair	Expansion Joints:	I - Inapplicable		
Comments:	Minor EFF at joint between old and new structure. Minor longitudinal cracking on old structure.				
DECK					
Condition:	F1 - Fair	Curbs:	F1 - Fair		
Hand Rail:	F1 - Fair	Roadway Condition:	F2 - Fair		
Approach Rail:	I - Inapplicable				
Comments:	Minor cracks in curbs. No approach rail.				
HYDROLOGY					
Water Velocity:	0 m/s	Ice Problem:	NA - Not Applicable		
Water Depth:	0 m	Scour Problem:	NA - Not Applicable		
Waterway:	03 - Not Applicable	Debris Problem:	NA - Not Applicable		
Comments:					
REPLACEMENT/REHABILITATION					
Next Rehab. Date:		Replacement Year:			
Antic. Rehab. Cost:	\$0	Replacement Cost:	\$0		
Recommendations:					
OBSERVATIONS					
Overall Condition:	F2 - Fair	Requires Further Inspection:	No		
Additional Observations:	Hazard signs missing Penstock bridge				

Department of Transportation and Infrastructure, Government of Newfoundland and Labrador 2026.