

		GOVERNMENT OF NEWFOUNDLAND AND LABRADOR Department of Transportation and Infrastructure		BRIDGE INSPECTION REPORT B02072025-4	
Date: 2/6/2025		Inspected By: T Upshall / M Button		Category: Eng. - Engineering	
BRIDGE INFORMATION					
Site:		1-195 - BROWNSDALE RIVER BRIDGE #1 - R			
SUBSTRUCTURE					
Condition:	G - Good	Bearings:	I - Inapplicable		
		Bearing Seat:	I - Inapplicable		
Comments:	Structure replaced in 2021 with precast concrete box culvert and recon block wingwalls.				
SUPERSTRUCTURE					
Condition:	G - Good	Expansion Joints:	I - Inapplicable		
Comments:					
DECK					
Condition:	G - Good	Curbs:	I - Inapplicable		
Hand Rail:	G - Good	Roadway Condition:	G - Good		
Approach Rail:	G - Good				
Comments:	New TL-4 concrete barrier and guiderail for structures. Hazard markers installed incorrectly.				
HYDROLOGY					
Water Velocity:	0 m/s	Ice Problem:	N - No Problem		
Water Depth:	0 m	Scour Problem:	N - No Problem		
Waterway:	01 - Adequate	Debris Problem:	N - No Problem		
Comments:					
REPLACEMENT/REHABILITATION					
Next Rehab. Date:	2040	Replacement Year:	2096		
Antic. Rehab. Cost:	\$0	Replacement Cost:	\$0		
Recommendations:					
OBSERVATIONS					
Overall Condition:	G - Good	Requires Further Inspection:	No		
Additional Observations:					

Department of Transportation and Infrastructure, Government of Newfoundland and Labrador 2026.