



Weekly Public Status Report of Oil and Gas Activities Onshore Newfoundland and Labrador

As of: November 7, 2011

EXPLORATION DRILLING PROGRAM

Well (Authority to Drill a Well)	Location (NAD 27)	Permit	Rig	Spud Date	Current Status
Vulcan Flat Bay Test Hole #6 (2011-116-01-03)	N 5 358 513 E 384 606	EP 03-106	Logan Drilling Duralite 800	October 3, 2011	Abandoned
Vulcan Flat Bay Test Hole #4 (2011-116-01-01)	N 5 359 930 E 383 525	EP 03-106	Logan Drilling Duralite 800	October 7, 2011	Abandoned
Vulcan Flat Bay Test Hole #8 (2011-116-02-02)	N 5 360 651 E 385 323	EP 96-105	Logan Drilling Duralite 800	October 11, 2011	Abandoned
Vulcan Flat Bay Test Hole #5 (2011-116-02-01)	N 5 361 123 E 383 208	EP 96-105	Logan Drilling Duralite 800	October 16, 2011	Abandoned
Vulcan Flat Bay Test Hole #9 (2011-116-02-03)	N 5 360 190 E 383 640	EP 96-105	Logan Drilling Duralite 800	November 1, 2011	Abandoned