
Line SR 005 Anguille Anomalies

Reefs observed in outcrop at approximately this level – estimated here based on stratigraphic location in the seismic section











Deer Lake Area







REQUEST FOR BIDS 2002 PARCELS - WITH SURFACE GEOLOGY





For illustrative purposes only.













Possible source rocks













Line DL 001








Line DL 001
















Vinland Line 001 – Deer Lake







Parsons Pond Area

