

		GOVERNMENT OF NEWFOUNDLAND AND LABRADOR Department of Transportation and Infrastructure		<b>BRIDGE INSPECTION REPORT</b> <b>B02012022-21</b>	
Date: 5/26/2021		Inspected By: Lynch R / Burge H		Category: Eng. - Engineering	
<b>BRIDGE INFORMATION</b>					
Site:		TCH-156 - GRAND FALLS/WINDSOR TCH PEDESTRIAN OVERPASS - R			
<b>SUBSTRUCTURE</b>					
Condition:	F2 - Fair	Bearings:	I - Inapplicable		
		Bearing Seat:	I - Inapplicable		
Comments:	Concrete box culvert. Paved bottom - walkway. Large pothole at LHS at end of structure.				
<b>SUPERSTRUCTURE</b>					
Condition:	I - Inapplicable	Expansion Joints:	I - Inapplicable		
Comments:	N/A				
<b>DECK</b>					
Condition:	I - Inapplicable	Curbs:	F2 - Fair		
Hand Rail:	I - Inapplicable	Roadway Condition:	F1 - Fair		
Approach Rail:	F2 - Fair				
Comments:	Settlement in surface outside of structure. Transverse cracks in asphalt corresponding with edges of crossing.				
<b>HYDROLOGY</b>					
Water Velocity:	n/a m/s	Ice Problem:	NA - Not Applicable		
Water Depth:	n/a m	Scour Problem:	NA - Not Applicable		
Waterway:	03 - Not Applicable	Debris Problem:	NA - Not Applicable		
Comments:	N/A				
<b>REPLACEMENT/REHABILITATION</b>					
Next Rehab. Date:		Replacement Year:			
Antic. Rehab. Cost:	\$0	Replacement Cost:	\$0		
Recommendations:	Install hand rail at top of head walls.				
<b>OBSERVATIONS</b>					
Overall Condition:	F2 - Fair	Requires Further Inspection:	No		
Additional Observations:	Centre light missing protective steel cage.				

Department of Transportation and Infrastructure, Government of Newfoundland and Labrador 2024.