

	GOVERNMENT OF NEWFOUNDLAND AND LABRADOR Department of Transportation and Infrastructure	BRIDGE INSPECTION REPORT B10282016-4	
Date: 10/28/2016	Inspected By: Alex Ford	Category: Eng. - Engineering	
BRIDGE INFORMATION			
Site:	2-158 - NORTH HARBOUR BRIDGE #2		
Route:	210-11	Overall Length:	12 m
Year Built:	1970	Est: No	Overall Width: 8 m
Year Last Rehab.:		Est: No	Roadway Width: 7 m
Region:	CENTRAL EAST	Sidewalk Width:	0 m
Jurisdiction:	Provincial	Clearance to R.D. or N.W.L.:	1.5 m
Type of Structure:	11 - Timber Bridge	Max Depth of N.W.L.:	1.5 m
Purpose of Structure:	03 - Over Navigable Waters	Spans:	
Type of Handrail:	03 - Timber Rail	<u>Span No.:</u>	<u>Length</u>
Roadway Surface:	02 - Asphalt	1	2.9
Alignment Vertical:	01 - Good	2	0
Alignment Horizontal:	01 - Good	3	0
Restrictions:	No	4	0
		5	0
		6	0
BRIDGE PHOTOS			
			
SUBSTRUCTURE			
Condition:	I - Inapplicable	Bearings:	I - Inapplicable
		Bearing Seat:	I - Inapplicable
Comments:			
SUPERSTRUCTURE			
Condition:	I - Inapplicable	Expansion Joints:	I - Inapplicable
Comments:			
DECK			
Condition:	I - Inapplicable	Curbs:	I - Inapplicable
Hand Rail:	I - Inapplicable	Roadway Condition:	I - Inapplicable

Approach Rail:	I - Inapplicable		
Comments:			
HYDROLOGY			
Water Velocity:	0.3 m/s	Ice Problem:	N - No Problem
Water Depth:	1.0 m	Scour Problem:	N - No Problem
Waterway:	01 - Adequate	Debris Problem:	N - No Problem
Comments:	Tidal.		
REPLACEMENT/REHABILITATION			
Next Rehab. Date:	2016	Replacement Year:	2016
Antic. Rehab. Cost:	\$0	Replacement Cost:	\$0
Recommendations:			
OBSERVATIONS			
Overall Condition:	I - Inapplicable	Requires Further Inspection:	No
Additional Observations:	Bridge replaced in 2016 with an aluminum pipe arch.		
LEGEND:			
Condition Definitions:		Problem Definitions:	
1 - *Good - [discontinued code].	F2 - Fair.	C - Unsafe (Closed to Public).	N - No Problem.
2 - *Fair - [discontinued code].	F1 - Fair.	U - Uninspectable.	P - Possible Problem.
3 - *Poor - [discontinued code].	P3 - Poor.	I - Inapplicable.	K - Known Problem.
4 - *Unsafe - [discontinued code].	P1 - Poor.		NA - Not Applicable.
G - Good.	P - Poor.		
Category Definitions:			
Maint. - Maintenance.			
Eng. - Engineering.			
Office - Bridge Office.			
PHOTO GUIDELINES:			
Inspection Photos:			
Please provide photos using guidelines below:			
<ul style="list-style-type: none"> ● Any item which inspector feels should be documented by photograph ● All items noted above as being P3, P1, P, or C ● Any evidence of known ice, scour, debris, waterway problems 			
INSPECTION PHOTOS			

Department of Transportation and Infrastructure, Government of Newfoundland and Labrador 2021.