

		GOVERNMENT OF NEWFOUNDLAND AND LABRADOR Department of Transportation and Infrastructure		BRIDGE INSPECTION REPORT B10132026-4						
Date: 9/29/2026		Inspected By: Scott Wight		Category: Eng. - Engineering						
BRIDGE INFORMATION										
Site:		TCH-086 - SOUTH BRANCH RIVER BRIDGE - R								
BRIDGE PHOTOS										
SUBSTRUCTURE										
Condition:		G - Good	Bearings:		G - Good					
			Bearing Seat:		G - Good					
Comments:										
SUPERSTRUCTURE										
Condition:		G - Good	Expansion Joints:		G - Good					
Comments:										
DECK										
Condition:		G - Good	Curbs:		I - Inapplicable					
Hand Rail:		G - Good	Roadway Condition:		G - Good					
Approach Rail:		F2 - Fair								
Comments:		Small crack in concrete barrier on northeast corner. Minor concrete deterioration on deck.								
HYDROLOGY										
Water Velocity:		0 m/s	Ice Problem:		N - No Problem					
Water Depth:		0 m	Scour Problem:		N - No Problem					
Waterway:		01 - Adequate	Debris Problem:		N - No Problem					
Comments:										
REPLACEMENT/REHABILITATION										
Next Rehab. Date:		Replacement Year:								
Antic. Rehab. Cost:		\$TBD	Replacement Cost:		\$TBD					
Recommendations:										
OBSERVATIONS										
Overall Condition:		G - Good	Requires Further Inspection:		No					
Additional Observations:										
LEGEND: <table border="0"> <tr> <td> Condition Definitions: 1 - *Good - [discontinued code]. 2 - *Fair - [discontinued code]. 3 - *Poor - [discontinued code]. 4 - *Unsafe - [discontinued code]. G - Good. </td> <td> F2 - Fair. F1 - Fair. P3 - Poor. P1 - Poor. P - Poor. </td> <td> C - Unsafe (Closed to Public). U - Uninspectable. I - Inapplicable. </td> <td> Problem Definitions: N - No Problem. P - Possible Problem. K - Known Problem. NA - Not Applicable. </td> <td> Category Definitions: Maint. - Maintenance. Eng. - Engineering. Office - Bridge Office. </td> </tr> </table> PHOTO GUIDELINES: Inspection Photos: Please provide photos using guidelines below: • Any item which inspector feels should be documented by photograph • All items noted above as being P3, P1, P, or C • Any evidence of known ice, scour, debris, waterway problems						Condition Definitions: 1 - *Good - [discontinued code]. 2 - *Fair - [discontinued code]. 3 - *Poor - [discontinued code]. 4 - *Unsafe - [discontinued code]. G - Good.	F2 - Fair. F1 - Fair. P3 - Poor. P1 - Poor. P - Poor.	C - Unsafe (Closed to Public). U - Uninspectable. I - Inapplicable.	Problem Definitions: N - No Problem. P - Possible Problem. K - Known Problem. NA - Not Applicable.	Category Definitions: Maint. - Maintenance. Eng. - Engineering. Office - Bridge Office.
Condition Definitions: 1 - *Good - [discontinued code]. 2 - *Fair - [discontinued code]. 3 - *Poor - [discontinued code]. 4 - *Unsafe - [discontinued code]. G - Good.	F2 - Fair. F1 - Fair. P3 - Poor. P1 - Poor. P - Poor.	C - Unsafe (Closed to Public). U - Uninspectable. I - Inapplicable.	Problem Definitions: N - No Problem. P - Possible Problem. K - Known Problem. NA - Not Applicable.	Category Definitions: Maint. - Maintenance. Eng. - Engineering. Office - Bridge Office.						
INSPECTION PHOTOS										